

RECORDS CODE SHEET
SND 4535 (Rev. 5-60)

NAVAL AVIATION SAFETY CENTER

GENERAL
(Card No. 1)

SUPPLEMENTARY
(Card No. 2)

Bureau Number	148222	16-21	Weather		16-21												
Reporting Custodian	919	22-24	Kind of Flight	1J	22-24												
Type of Duty	12	25-26	Relative Wind - Direction	U	25												
Major Command		27	Relative Wind - Velocity	1	26												
Aircraft Damage	A	28	Relative Wind (Old Code - Not in Use)		27												
Aircraft Injury	A	29	Clearance	2	28												
Maneuver prior to Accident	G	30	Time of Day	2	29												
First Accident type	S1	31-32	Number of other Aircraft		30												
First Accident phase	31	33-35	Altitude of Occurrence		33-35												
Second Accident type	C3	36-37	Distance from Field	Coded on	38-40												
Second Accident phase	A2	38-40	Length of Runway	forced landings	41-42												
Type of Operation	3	41-42	Field Elevation	only	43-45												
Contributing Cause Factors	1M	43-47	Non-Navy Injury ("R")		47												
Pilot Factor, First	O1	48-49	Number of "A" or "L" or "M" Injury	41	48-49												
Pilot Factor, Second	P9	50-51	Number of "B" Injury		50-51												
Pilot Factor, Third	O5	52-53	Number of "C" Injury	41	52-53												
First other Personnel Factor		54-55	Number of "D" Injury		54-55												
Second other Personnel Factor		56-57	Number of "E" Injury		56-57												
Primary Major Material Factor	D	58	Location	A1KNGVL	62-68												
Secondary Major Material Factor		59	Facility Data	KOP	69-74												
Design		60	<table border="1"> <tr> <td>Don't Count</td> <td>Enemy Action</td> <td>Other Aircraft</td> </tr> <tr> <td>I.D. NO.</td> <td>1 2 3 4 5 6 7 8</td> <td>9 10 11 12 13 14 15</td> </tr> <tr> <td>YR</td> <td>MO</td> <td>DAY</td> </tr> <tr> <td>TYP</td> <td>SEQ</td> <td>Model</td> </tr> </table>			Don't Count	Enemy Action	Other Aircraft	I.D. NO.	1 2 3 4 5 6 7 8	9 10 11 12 13 14 15	YR	MO	DAY	TYP	SEQ	Model
Don't Count	Enemy Action	Other Aircraft															
I.D. NO.	1 2 3 4 5 6 7 8	9 10 11 12 13 14 15															
YR	MO	DAY															
TYP	SEQ	Model															
Facilities		61	ACCIDENT DAMAGE	A													
Special Data & Cond.	8AG	62-68	ACCIDENT INJURY	A													
Type of Flight Hazard		69	FISCAL YEAR	7													
Pri. Cause/Avoidable Inc. or Flt Haz or Gr Act	1	70	SPECIAL ATTN: ("X")														
Recommendation Code		71-72	IBM: The above Fields are to be punched in all Coded Code														
Carrier Hull Number		73-74	Model Code														
No Personnel Card ("R")		80	27														

PERSONNEL STATISTICS
(Card No. 3)

File Number	16	17	18	19	20	21	Rank/Rate	Br Service	Age	Yrs Experience	Status	Position	Inj to Ind	Abandon A/C	Pilot Factor Involved	Trainer Utilization	Instr. Card	Total Time All Models	All Models 3 Months	All Series This Model	All Ser Mod 3 Months	CV Landings	Instrument Hours	Nite Hours	Total Time Jet
03 (b) (6)							45C6A1C21											1610	33	49		031	887		
04 SECKINGER							31JJC2A24											1240	107	1		090	531		

Dual Pilot Name 16 17 18 19 20 21
File Number (b) (6)

IBM: PERSONNEL CODED ON REVERSE SIDE ☐

CODED che REVIEWED ITM LOGGED js PUNCHED js VERIFIED _____ REVIEWED _____ REPUNCHED _____

CODE SHEET REVIEWED BY CLASS DESK ANALYST

(Initials)

(Date)

16-7-1961

1 R DEPT CODE SHEET

☐

Don't
Count

☐

Other
Aircraft

75	76	77	78	79
1	2	7	6	2

Year	Month	Day	Type Occurrence Sequence	Damage Injury	Model Aircraft
1	2	3	4	5	6
1	4	5	2	5	1

Bureau Number

1	4	8	2	2	2
---	---	---	---	---	---

NARRATIVE BRIEF

16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70															
<p>DURING NO FLAP TO PILOT WAS UNABLE TO RAISE NOSE FOR TO AND ATTEMPTED TO ABORT AS END OF RW WAS APPROACHED PILOT PULLED CURTAIN EJECTING BOTH PILOTS THROUGH CANOP DUAL PILOT WAS KILLED BECAUSE SEAT FAILED TO SEPARATE DUE TO IMPROPER RIGGING</p>																																																																					

Prepared by

(b) (6)

Reviewed

Punched

JUL 14 1961

Verified

Note to IBM: Route code sheet to Open File upon completion of Brief Cards.

U. S. NAVAL AVIATION SAFETY CENTER
U. S. NAVAL AIR STATION
NORFOLK 11, VIRGINIA

NASC/113/rop

Ser: 324

APR 30 1962

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAV INST 3750.6D

From: Commander, U. S. Naval Aviation Safety Center
To: Commanding Officer, Training Squadron SEVEN

Subj: VT-7 AAR ser 6-61 concerning T2J-1 BuNo 148222 accident occurring
25 May 1961, pilot (b) (6)

1. The subject report and all endorsements thereon have been reviewed. The Naval Aviation Safety Center concurs with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.
2. The cause of this accident has been recorded by the Center indicating the pilot as the single contributing factor.

(b) (6)

By direction

Copy to:
BUWPS (C-13) 2 copies
CNATRA
CNABATRA
CMC (CODE AAP)
BUWPSREP COLUMBUS
CO, NPU EL CENTRO
CO VT-4

4

C-1312:HWM/88

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST 3750.6D

27 FEB 1962

FOURTH ENDORSEMENT on TRARON SEVEN AAR ser 6-61, concerning T2J-1,
BuNo 148222, accident occurring 25 May 1961, Pilot (b) (6)

From: Chief, Bureau of Naval Weapons
To: Commander, U. S. Naval Aviation Safety Center

Subj: Aircraft Accident Report; forwarding of

1. Forwarded, concurring with paragraph 2. of the second endorsement.
2. Anti-suffocation devices for pressure oxygen systems have been and will continue to be investigated. To date, all proposals and developments have jeopardized the system in normal operation.

(b) (6)

(b) (6)

BY direction

Copy to:
CNATRA
CNABATRA
CO, VT-7

5

ORIGINAL

Code 05

24 JUL 1961

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 70, OPNAVINST 3750.6D

THIRD ENDORSEMENT on TRARON SEVEN AAR ser 6-61, concerning T2J-1, BuNo 148222, accident occurring 25 May 1961, Pilot (b) (6)

From: Chief of Naval Air Training
To: Commander, U. S. Naval Aviation Safety Center
Via: Chief, Bureau of Naval Weapons

Subj: Aircraft Accident Report; forwarding of

1. Forwarded, concurring in the comments and recommendations of the Board as modified by the forwarding endorsements. Concur in the action and comments indicated in the forwarding endorsements.

(b) (6)

Copy to:
CNC (Code AAP)
BUWEPREP Columbus
OinC, NPU, El Centro
CINADTRA
CO TRARON FOUR
CO TRARON SEVEN (4)

By direction

6



U. S. NAVAL AVIATION SAFETY CENTER
U. S. NAVAL AIR STATION
Norfolk 11, Virginia

AVSAFE
NASC/531/gh
9 August 1961

From: Commander, U. S. Naval Aviation Safety Center

To: Chief of Naval Air Training

Subj: ~~SPARC~~ Original AAR Serial 6-61 Concerning 22J-1,

Bureau No. 125725 accident occurring 25 May 1961,

Pilot (b)(6)

Ref: (a) OPNAVINST 3750.6D

1. The subject AAR was forwarded to your command on 25 June 61 by Chief of Naval Air Training.
2. Request status of your endorsement and original AAR.
3. Your attention is invited to Para 46d(2) of Reference (a).

(b)(6)

By direction

Code 05
14 August 1961

FIRST ENDORSEMENT

From: Chief of Naval Air Training

To: Commander, U. S. Naval Aviation Safety Center

Subj: VT-7 AAR Serial 6-61

Encl: (1) Copy of CNATRA's THIRD ENDORSEMENT on subject AAR of 24 July 1961

1. Subject AAR was endorsed 24 July 1961 and mailed to the Chief, Bureau of Naval Weapons. NAVAVSAPCEN was inadvertently omitted from the copy to addressee. A copy of CNATRA's endorsement is forwarded as enclosure (1).

(b)(6)

By direction

7

ORIGINAL

Code 05
29 JUN 1961

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70 OF OPNAV INSTRUCTION 3750.6D

SECOND ENDORSEMENT on TRARON SEVEN AAR 6-61, concerning T2J-1, BuNo 148222, occurring 25 May 1961, Pilot (b) (6)

From: Chief of Naval Air Basic Training
To: Commander, U. S. Naval Aviation Safety Center
Via: (1) Chief of Naval Air Training
(2) Chief, Bureau of Naval Weapons

Subj: Aircraft Accident Report; forwarding of

1. Readdressed and forwarded, concurring in the comments and recommendations of the Aircraft Accident Board as modified by paragraph 2 of the First Endorsement.
2. In regards to the AAR Board recommendation #2, the Handbook of Inspection Requirements is not designed to enumerate each item to be inspected during an intermediate or major inspection but rather to call attention to areas that require work. Details concerning required inspections should be obtained by reference to applicable sections of the Handbook of Maintenance Instructions. In areas where the HMI is not considered detailed enough to satisfy command requirements inspection procedures should be further amplified by the dissemination of Continuing Action Maintenance Instructions.
3. It is recommended that the Bureau of Naval Weapons take action on AAR Board recommendation #4.
4. The pilot in this accident violated several squadron standard operating procedures as well as one OPNAV Instruction. Squadron SOPs have little value if they are not rigidly adhered to by all personnel. This is especially true in the Training Command where student pilots are developing flying procedures which will remain with them throughout their career.
5. The Commanding Officer, TRARON SEVEN is requested to make sufficient spot checks to insure that standard operating procedures are being adhered to by personnel in TRARON SEVEN.

Copy to:
BUWEPS (C-13) (Direct)
COMNAVAVSACFEN (Direct)
BUWEPS REP, Columbus
CMC (Code AAP)
OinC, NPU
CO, TRARON FOUR
CO, TRARON SEVEN (2)

C. H. Duerfeldt
C. H. DUERFELDT

ORIGINAL

ORIGINAL

23 JUN 1961
23 JUN 1961

FIRST ENDORSEMENT on VT-7 AAR Ser 6-61, Concerning T2J-1, BUNO 148222
Accident occurring 25 May 1961, Pilot (b) (6)

From: Commanding Officer, Training Squadron SEVEN,
Naval Auxiliary Air Station, Kingsville, Texas
To: Commander, Naval Aviation Safety Center
Via: (1) Chief of Naval Air Basic Training
(2) Chief of Naval Air Training

23 JUN 1961

Subj: VT-7 AAR Ser 6-61; forwarding of

Encl: (10) Addendum to Maintenance Officer's Statement

1. Forwarded, concurring with the recommendations of the board.
2. It is considered that the primary contributing cause of this accident is pilot factor rather than the suspected failure or malfunction of the elevator control system. There is no concrete evidence to support the latter contention. The pilot's non compliance with standard operating procedures and aviation common sense bred uncertainty, doubt and indecision during one of the most critical parts of the flight - take off. As a result, the pilot was incapable of making a quick analysis of the situation and taking the sound action necessary to handle the airplane.
3. The Maintenance Officer's statement did not comment on either the ejection seat or the gas line to the canopy actuator. Enclosure (10) to this endorsement is an addendum to the Maintenance Officer's statement and corrects this deficiency.
4. Enclosure (2) contains a resume of the pilot's flying experience. He had not had any accidents in his previous flying career.
5. The importance of using check lists and of adhering to standard operating procedures has been pointed out again to all pilots. To ignore such good practices is to invite the same kind of confusion and doubt as occurred during this accident.
6. To combat ejection seat maintenance errors the recommendations of the board will be implemented. Further, the proposals outlined in the "Weekly Summary of Aircraft Accidents" (8-14 May) will be adopted.


R. F. REGAN

9

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70 OPNAVINST 3750.6D

ORIGINAL

PART I - GENERAL

1. A/C ACCIDENT BOARD APPOINTED BY Commanding Officer VT-7		2. DATE OF ACCIDENT 25 May 1961		TIME (LZT) 0848S	3. SERIAL NUMBER AAR 6-61
4. TO: COMMANDER NAVAL AVIATION SAFETY CENTER		5. ENCLOSURES (1) PILOT'S STATEMENT			
6. VIA (1) C.O. VT-7		(2) RESUME OF PILOTS FLYING EXPERIENCE			
(2) CHIEF OF NAVAL AIR BASIC TRAINING		(3) WITNESS STATEMENTS			
(3) CHIEF NAVAL AIR TRAINING		(4) MAINTENANCE OFFICER'S STATEMENT			
(4)		(5) DIAGRAMS			
(5)		(6) PHOTOS			
(6)		(7) AIRCRAFT CRASH FIRE REPORT			
7. REPORTING CUSTODIAN (if different than item 1. above) SAME		(8) DD-175			
9. KIND OF FLIGHT LJL		(9) MOR (WITH ORIG ONLY)			
10. TIME OF DAY <input type="checkbox"/> DAWN <input checked="" type="checkbox"/> DAY <input type="checkbox"/> DUSK <input type="checkbox"/> NIGHT		8. ACTIVITY OPERATING A/C (if different than item 7.1) SAME			
11. LOCATION OF ACCIDENT (SOUTH FIELD) NAAS KINGSVILLE, TEXAS		12. ELEVATION ABOVE SEA LEVEL 52			
13. PHASE OF LAST TAKE OFF NAAS KINGSVILLE		14. CLEARED FROM NAAS KINGSVILLE TO NAS PENSACOLA FLA			
15. TYPE CLEARANCE <input type="checkbox"/> IFR <input checked="" type="checkbox"/> VFR <input type="checkbox"/> DVFR <input type="checkbox"/> LOCAL <input type="checkbox"/> OPERATIONAL <input checked="" type="checkbox"/> AIRWAYS <input checked="" type="checkbox"/> DIRECT <input type="checkbox"/> OTHER (Specify)					
16. TIME IN FLIGHT 0		17. TYPE ACCIDENT S-1 RAN OFF END OF RUNWAY		18. PHASE OF FLIGHT 3-FLAPS UP TAKE OFF	
19. MODEL T2J-1		20. SERIAL NO. 118222		21. DAMAGE TO A/C <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F	
22. DOLLAR COST 503,000		23. AIRSPEED (Kts.) REACHED 110 to 115 KTS		24. A/C WEIGHT 11,600	
25. LIST MODEL, SER NR, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete on OPNAV FORM 3750-1 for each A/C involved) NONE					

1. NAME (Last, first and middle initials) PILOT (at controls at time of accident) (b) (6)		2. RANK CAPT	FILE SER. NO. (b) (6)	DESIG. NATOR (b) (6)	BRANCH (OR SERVICE) USMC	3. AGE 31	4. YRS. OF EXP. DVA 6	5. BILLET PILOT	6. POSITION FRONT COCKPIT C	7. INJURY CODE
DUAL PILOT SECKINGER, NEIL V.		LCDR			USN	32	17	DUAL PILOT	REAR COCKPIT A	
PERSONNEL		8. OFT - OPERATIONAL FLIGHT TRAINER		9. CPT - COCKPIT PROC. TRAINER		10. UNIT TO WHICH PERSONNEL ARE ATTACHED		11. TYPE INSTRUMENT CARD		
		AVAILABLE		USED						
PILOT		YES		X		VT-7		<input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL		
		NO		X						
DUAL PILOT		YES		X		VT-7		<input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL		
		NO		X						
12. ITEM		PILOT		DUAL PILOT		ITEM		PILOT DUAL PILOT		
ALL MODELS		1621.9		14036.5		CV LANDINGS DAY/NIGHT		6/0 113/0		
ALL MODELS IN LAST 12 MONTHS		351.6		191.1		FLCP LANDINGS DAY/NIGHT		120/0 NOT RECOR IN LOG BO		
ALL MODELS IN LAST 3 MONTHS		108.2		19.9		INSTRUMENT HOURS LAST 3 MONTHS		2.8 8.5		
ALL SERIES THIS MODEL (Item 29)		A/C		330.7		27.7		NIGHT HOURS LAST 3 MONTHS		
		OFT / CPT		2.0		7.0		18.4 5.1		
ALL SERIES THIS MODEL LAST 12 MONTHS		A/C		319.2		63.6		TOTAL HELO. HRS. (Helo. AAR Only)		
		OFT / CPT		2.0		7.0		TOTAL JET HOURS (Jet AAR Only)		
ALL SERIES THIS MODEL LAST 3 MONTHS		A/C		97.8		15.5		LAST FLIGHT, ALL SERIES THIS MODEL		
		OFT / CPT		0.0		0.0		DATE 23 MAY 61 23 MAY 61		
13. NAME (Last, first and middle initials)		DVA		RANK		FILE/SERVICE NO		ORG. TO WHICH ATTACHED		INJURY CODE
1. NONE										BILLET
2.										POS.
3.										ION
4.										
5.										

1. CEILING 1000 FT		2. VISIBILITY 10 MI		3. WIND DIRECTION & VELOCITY 330 KLT/7 KTS		4. TEMPERATURE 84		5. DEW POINT 74		6. ALTIMETER SETTING 29.85	
7. OTHER WEATHER CONDITIONS (winds aloft, icing levels, sea state, etc. if pertinent to accident)											

ORIGINAL

✓ FACTOR		✓ FACTOR		✓ FACTOR	
X PILOT		LANDING SIGNAL OFFICER		X MATERIAL FAILURE OR MALFUNCTION	
CREW		OTHER PERSONNEL (Specify)		DESIGN	
SUPERVISORY PERSONNEL		ADMINISTRATIVE		ROLLING AND PITCHING DECK/ ROUGH SEAS	
MAINTENANCE PERSONNEL		AIRPORT OR CARRIER FACILITIES		UNDETERMINED	
SERVICING PERSONNEL		WEATHER		OTHER (Specify)	

FOR ACCIDENTS ABOARD DEPLOYED CARRIER (Complete following Section on Pilot)

1. DATE DEPLOYED N.A.		2. DAY - HOURS/LANDINGS LOGGED SINCE DEPLOYED N.A.		3. DAY - HOURS/LANDINGS LOGGED LAST 30 DAYS N.A.	
4. INSTRUMENT HRS. LOGGED SINCE DEPLOYMENT N.A.		5. NIGHT - HOURS/LANDINGS LOGGED SINCE DEPLOYED N.A.		6. NIGHT - HOURS/LANDINGS LOGGED LAST 30 DAYS N.A.	

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA

1. A/C HISTORY	DATE OF MANUFACTURE	SERVICE TOUR	MONTHS IN THIS TOUR	TOTAL NO. OF OVERHAULS	FLIGHT HRS SINCE LAST OVERHAUL	FLIGHT HRS SINCE ACCEPTANCE	TYPE CHECK LAST PERFORMED	FLIGHT HOURS SINCE LAST CHECK	NO. OF DAYS SINCE LAST CHECK
1	9 JUN 1961	1st	1	0	0	215.4	INTERMEDIATE	60.6	37
ENGINE MODEL		ENGINE SERIAL NO.							
2. ENGINE HISTORY									
1									
2									
3									
4									

a. DID FIRE OCCUR? <input type="checkbox"/> BEFORE ACCIDENT <input checked="" type="checkbox"/> AFTER ACCIDENT <input type="checkbox"/> DID NOT OCCUR				b. DID EXPLOSION OCCUR IN FLIGHT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
c. CHECK IF APPLICABLE <input type="checkbox"/> AMP FOR SERIAL				d. HAS DIR BEEN REQUESTED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		e. FAILED COMPONENTS INVOLVED ELEVATOR BOOST ACTUATOR	

CHECK ITEMS PRESENT IN THIS ACCIDENT

a. <input type="checkbox"/> A/C DESIGN	d. <input type="checkbox"/> UNDETERMINED	g. <input type="checkbox"/> SURFACE FACILITIES
b. <input type="checkbox"/> A/C EQUIPMENT	e. <input type="checkbox"/> TECHNICAL INSTRUCTION	h. <input type="checkbox"/> HUMAN ENGINEERING (e.g., Cockpit configurations, etc.)
c. <input type="checkbox"/> MAINTENANCE	f. <input type="checkbox"/> OTHER (Specify) _____	

a. ALTITUDE AT MALFUNCTION DURING TAKE-OFF ROLL	b. AIR SPEED	c. OPERATING TEMP.	d. WEIGHT OF A/C	e. C.G. (% MAC)	f. KIND OF FUEL	g. FUEL PRESSURE
N.A.	100 Kts	N.A.	11,600	N.A.	N.A.	N.A.
h. EVIDENCE OF FUEL CONTAMINATION N.A.			i. CRUISE OF ENGINE FAILURE OR FLAME OUT N.A.			
j. FUEL CONTROL REGULATOR/CARBURETOR (List Stock and Ser. nos., give time since new or overhauled) N.A.					k. EXTERNAL STORES ABOARD A/C NONE	

(If additional space is necessary, attach additional sheets)

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

AIRCRAFT ACCIDENT REPORT

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA (Cont'd)

1. GENERAL. BASIC FACILITIES INVOLVED. DESCRIBE EFFECT ON ACCIDENT IN THE ANALYSIS SECTION OF THE REPORT

a. CLEARANCE AUTHORITY	i. WATER LANDING	q. CRASH AND RESCUE
b. FLIGHT PLANNING INFORMATION SOURCE	j. APPROACH ZONE	r. SEARCH AND RESCUE
c. LANDING AIDS (GOAL, CA, H.S., etc.)	k. END ZONE (Over run)	s. CATAPULT
d. TRAFFIC CONTROL TOWER (Field or Ship)	l. SHOULDERS	t. ARRESTING GEAR (Carrier)
e. APPROACH AND ENROUTE AIDS TO NAVIGATION	m. TAXIWAY	u. BARRIER OR BARRICADE (Field or Ship)
f. RUNWAY WATCH	n. PARKING AREA	v. FLIGHT DECK
g. LANDING SIGNAL OFFICER	o. EMERGENCY ARRESTING GEAR (Runway)	w. MIRROR
h. RUNWAY	p. A/C SERVICING, HANDLING AND DIRECTING (Field or Ship)	x. OTHER (Specify)

a. EQUIPMENT INVOLVED: ☐ CATAPULT ☐ ARRESTING GEAR

b. PRESSURE SETTINGS *N/A* c. WIND OVER DECK *N/A* d. RELATIVE HEADWIND *N/A* e. APPROACH SPEED (SPN - 12 READING) *N/A*

f. MARK NUMBER *N/A* g. MODEL NUMBER *N/A* h. LOCATION ON SHIP *N/A* i. LAUNCHING BRIDLE AND CONFIGURATION USED *N/A*

j. CATAPULT / ARRESTING GEAR BULLETINS OR NODROGRAMS USED *N/A*

k. THIS PORTION SHALL BE COMPLETED WHENEVER (1) A MAJOR AIRCRAFT ACCIDENT INVOLVES ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT, OR (2) AN AIRCRAFT ACCIDENT INVOLVES MALFUNCTIONING OF ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT. MINOR ACCIDENTS OR ROUTINE DAMAGE TO CABLES, WELDINGS AND OTHER EXPENDABLE COMPONENTS NEED NOT BE REPORTED.

ENGAGED	DECK RUNOUT (FT.)	RAM TRAVEL (IN.)	CONTROL VALVE SETTINGS		ACCUMULATED OR PRESSURE (PSI)	COMMENTS (For cable failure specify number of landings and months in service)
			CONSTANT PRESSURE			
			DOSE (P.S.I.)	RATIO		
DECK PENDANT	<i>N/A</i>					
DECK PENDANT						
BARRIER						
BARRIER						
BARRICADE						

PART SECTION	ITEM	PART III REMARKS (Continue on additional sheets)	COPY DISTRIBUTION
			2CC NAVJMSAFECEN DIRECT 1CC BUMERS DIRECT 1CC CHATRA & ICR DIR 1CC CHATRA & ICR DI 1CC BUMERS REP COLONE DIRECT 1CC TRACON FOUR DIRECT 1CC CMC (CODE AAP) 1CC OINC NAVAL PARA- CHUTE UNIT
COST DAMAGE TO:		GOVERNMENT PROPERTY <i>NONE</i>	DATE SUBMITTED TO C & <i>6/14/61</i>
		PRIVATE PROPERTY <i>NONE</i>	

PART IV - SIGNATURES	
SAFETY OFFICER <i>(b)(6)</i>	ORGANIZATION OFFICER <i>(b)(6)</i>
UNIT BILLET	UNIT BILLET

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

PART V THE ACCIDENT

ORIGINAL

On 25 May 1961, CAPT (b) (6) signed out for T2J-1, bureau number 1148222 with LCDR SECKINGER as dual pilot for a ferry flight from NAAS KINGSVILLE, TEXAS to NAS PENSACOLA, FLORIDA.

The aircraft was pre-flighted by both pilots and no discrepancies were noted. The pilots strapped in with CAPT (b) (6) in the front cockpit and LCDR SECKINGER in the rear cockpit.

CAPT (b) (6) went over the pre-start check-off list and started the aircraft. The start was normal and CAPT (b) (6) went over his pre-taxi check-off list. He noted that the speed brakes did not extend when he pressed the switch to extend the speed brakes. The speed brakes indicator would show barber pole as he pressed the switch and then would immediately show in when he let go of the switch. A communications check on the intercommunications system was made and it worked normal. The oxygen masks were not fully put on by either pilot.

CAPT (b) (6) then taxied out to the duty runway completing his pre-take-off check-off list while taxiing except for the canopy and his shoulder harness.

CAPT (b) (6) requested and received clearance for take-off. As he taxied into position for take-off, he closed the canopy and locked his shoulder harness and put the flaps up for a flaps up take-off.

CAPT (b) (6) applied full throttle control while holding his brakes and as soon as the engine tachometer indicated 100% RPM, CAPT (b) (6) released the brakes and started the take-off roll.

CAPT (b) (6) noted the oil pressure was low (estimate 70 LBS pressure) and tried to tell LCDR SECKINGER in the rear cockpit about it. He held his oxygen mask over his face with his left hand as he pushed the intercom switch to "CALL" but was unable to get a response from LCDR SECKINGER. The other instruments indicated the engine was operating normally.

LCDR SECKINGER spoke on the intercom shortly after this, but CAPT (b) (6) did not understand what was said.

The take-off roll continued until 100 kts was reached and CAPT (b) (6) tried to raise the nose to take-off attitude. The nose would not come up even though an airspeed of 110 to 115 kts had been attained. CAPT (b) (6) tried a second time to raise the nose to take-off attitude, but to no avail.

When the nose did not come up on this second attempt, CAPT (b) (6) decided to abort the take-off. He reduced power to idle, turned off some switches and reached for the hook, but he saw he was past the runway arresting gear. He pulled the stick full back and applied full brake and saw he couldn't stop the aircraft before going off the end of the runway.

ORIGINAL

Inasmuch as there was no runway over-run, CAPT (b) (6) pulled the ejection curtain at the end of the runway. The ejection control was in the front cockpit and both pilots were ejected through the canopy.

CAPT (b) (6) section of the ejection system worked as it was designed to do, with the exception of the canopy. The distance from point of initiation to touchdown was 624 feet. LCDR SECKINGER went 599 feet from the end of the runway in the seat. Seat separation did not occur due to the fact that the striker ~~450~~ pivot clevis pin in the aneroid linkage was missing.

The aircraft rolled off the end of the runway into a deep gully and came to rest 491 feet from the end of the runway. The aircraft caught fire immediately. The crash crew arrived on the scene shortly thereafter and took charge.

PART VI DAMAGE TO THE AIRCRAFT

The aircraft was completely destroyed by the fire after it went into the gully.

It is estimated that the aircraft was moving at about 70 kts or more as it approached the embankment of the gully. The right main landing gear was collapsed on a concrete drainage block at the edge of the embankment.

The aircraft went over the embankment and the right wing and nose hit the other side of the gully, which ran at about a 20° angle to the aircraft's path over the ground. The aircraft slid for approximately 80 feet as it caught fire and burned.

The extensive damage to the aircraft was due to its inaccessibility to fire fighting equipment. (see enclosure 6A and 6C.).

PART VII THE INVESTIGATION

During the investigation, the following facts were established:

1. Pre-Flights

- a. A proper pre-flight of the aircraft was conducted by both pilots and no discrepancies were noted.
- b. The pre-taxi check-off list was performed while taxiing out, which is contrary to squadron S.O.P. It was noted by CAPT (b) (6) that the speed brakes would not extend. The speed brake indicator showed "barber pole" when the speed brake switch was pushed to ~~IN~~ and when the switch was released, the speed brake indicator would immediately indicate IN. The hydraulic pressure indicator showed 3000 lbs pressure.
- c. The intercommunications system was checked by the pilots and worked normally.
- d. The pre-take-off check-off list was performed while taxiing out to the duty runway. This practice is also contrary to squadron S.O.P.

ORIGINAL

e. The aircraft was taxied into position for take-off, while the canopy was being closed and while CAPT (b) (6) locked his shoulder harness. Both of these items are on the pre-take-off check list and should have been completed prior to taking the runway.

f. The oxygen masks were not put on and the intercom switches were on cold mike. (Contrary to OPNAV Instruction & Squadron S.O.P.)

g. CAPT (b) (6) raised the flaps for a flaps up take-off. Contrary to Squadron S.O.P.

2. Take-Off Roll

a. Power was applied to 100% RPM and as soon as it was reached, the take-off roll was started. Squadron S.O.P. requires a complete check of engine instruments prior to releasing the brakes for take-off roll. The engine instruments were not checked prior to starting the take-off roll. CAPT (b) (6) noted the oil pressure was low, however all other instruments were normal on the roll.

b. CAPT (b) (6) tried to contact LCDR SECKINGER on the intercom to tell him about the low oil pressure, but was unable to contact him.

c. At 100 kts, CAPT (b) (6) tried to raise the nose of the aircraft to take-off attitude. The nose did not come up and even though an estimated speed of 110 to 115 kts had been attained.

d. CAPT (b) (6) decided to abort; cut power to idle, turned some switches off, applied brakes and reached for the hook handle. The aircraft had already passed the runway arresting gear when the pilot reached for the hook handle. The arresting gear is 1500 feet from the upwind end of a 6,000 foot long runway.

e. CAPT (b) (6) couldn't stop so he pulled the stick all the way back for more braking action and reached for the gear handle thinking he could stop the aircraft with the gear up in the overrun. On the last 800 feet of the runway there were light traces of rubber from the main gear tires.

f. CAPT (b) (6) then realized there was no overrun and initiated ejection at the end of the runway. Ejection control was in the front cockpit, therefore, CAPT (b) (6) had ejection control for both pilots.

g. CAPT (b) (6) went through the air head first after seat separation and did not feel the shock of the parachute opening.

h. CAPT (b) (6) hit a boundary fence and small branches before he landed on the ground 624 feet from the end of the runway.

i. LCDR SECKINGER did not separate from his seat and he came to rest in the seat 599 feet from the end of the runway.

ORIGINAL

3. Ejection system.

a. Rear seat S/NH-407

- (1) Neither face curtain initiator (T-30E1) fired.
- (2) Neither face curtain cable cutter fired.
- (3) Harness release gun was not fired.
- (4) Neither the seat bottom bladder nor its initiator (T31E1) inflated or fired.
- (5) Neither back bladder nor its initiator T-31E1) inflated or fired.
- (6) The "D" ring handle was pulled and the 2 (T-30E1) initiators were fired.
- (7) The seat drogue gun was fired.
- (8) The aneroid unit - Arming pin was not pulled.
- (9) Evidence strongly supports the fact that no pivot pin was in the striker bellcrank at the time of ejection. (See enclosures 6H and 6I) Striker bellcrank engagement with the striker pin on the seat bulkhead produced sufficient rotation to pull firing pin from drogue gun, but the stroke was not sufficient to pull the aneroid arming pin.

b. Front seat - S/N H-406

- (1) Both face curtain initiators (T 30E1) were fired.
- (2) Both face curtain cable cutters fired and the wire lines on the face curtain were properly cut.
- (3) The "D" ring handle was actuated and both (T-30E1) initiators were fired.
- (4) The drogue gun was fired.
- (5) The aneroid unit functioned properly.
- (6) The harness release gun fired rotating the harness release bellcranks the required distance to release the two lap belt release pins and the shoulder harness pin.
- (7) Both back and seat bottom bladders and their respective (T-31E1) initiators actuated properly.

ORIGINAL

(C) This total seat system functioned as required.

c. Canopy

- (1) The gas line to canopy actuator shows no evidence of having been attached (see enclosure 6J)
- (2) There were no signs around the gas inlet port of the canopy actuator that ballistic gas had reached this point.
- (3) The canopy actuator screw jack was nine threads up from the fully closed position.
- (4) Ejection was through the canopy.

d. General

- (1) The trajectory to be realized for a speed range between 90 to 110 kts would be as follows:
 - (a) Pilot - 500 to 550 feet to point of touchdown.
 - (b) Seat - Approximately 400 - 450 feet.
- (2) Review of trajectory and distance measured in relation to CAPT (b) (6) shows the trajectory to be as designed.
- (3) Due to separation not occurring on the rear seat, the trajectory would be longer due to the seat-man combination weight, which would result in a slower deceleration and therefore longer horizontal distance travel.

4. Elevator Control System:

- a. The elevator control cables from the boost actuator in the tail to the shackle aft of the elevator control linkage were intact.
- b. The elevator control linkage from this station forward was destroyed by the intense fire.
- c. The elevator boost actuator is being sent to O & R, Pensacola, Florida to determine if it malfunctioned.
- d. The elevator trim actuator on the port side was recovered and was found in the neutral position which is correct for take-off.
- e. The starboard trim actuator was not recovered.
- f. There was boost hydraulic pressure available to the system as shown by the indicator.

5. Engine and involved component parts.

ORIGINAL

- a. All the engine bearings had oil in them and showed no sign of undue wear.
 - b. The oil pump was in the gear train and no shafts were sheared so it is assumed the oil pump was working correctly.
 - c. The engine was seized due to impact damage to the gear train and the compressor shroud.
 - d. The oil pressure guage indicated low oil pressure probably because of instrument malfunction and not actual low oil pressure.
6. Speed brakes.
- a. The speed brakes were IN and locked when recovered from the wreckage.
 - b. Due to the extensive fire damage the cause for the speed brakes not extending could not be determined.
7. Take-off computations and tests conducted.
- a. The pilot's handbook does not contain take-off charts for flaps up, therefore, the take-off distance and lift off speed were obtained from the Field Engineering Trainer Group, North American Aviation Inc., Columbus, Ohio.
 - (1) The given conditions were the same as at the time of the accident:
 - (a) Runway temperature 84°.
 - (b) Seven knot head wind.
 - (c) Gross weight 11,600 lbs.
 - (d) 52 feet above sea level
 - (e) Flaps up.
 - (2) The lift off speed was determined as 110-125 kts and the take-off distance as 3000 feet maximum.
 - (3) The lift off speed and take-off distance for the above conditions, but with flaps down is 98 kts and 2300 feet. Taken from charts in Pilots Handbook.
 - b. A take-off test was conducted.
 - (1) The following given conditions were used:
 - (a) Runway temperature 84.6°

ORIGINAL

- (b) 10 - 15 kts headwind
- (c) Gross weight 11,600 lbs.
- (d) 60 lbs of baggage in nose of aircraft. (CAPT (b) (6) aircraft had 58 lbs of baggage).
- (e) 52 feet above sea level
- (f) Flaps up.
- (g) Stick was brought back at 100kts.

(2) The results.

- (a) Nose of the aircraft came up at 100 kts.
- (b) Aircraft came off the deck at 115 kts.
- (c) The take-off roll distance was 2600 feet.
- (d) No unusual stick feel was encountered.

8. Stopping distances (From Pilot's Handbook)

- a. From 98 kts - 1720 feet.
- b. From 115 kts - 2320 feet. (Curves were extended beyond graphed part of chart and interpolated).

PART VIII THE ANALYSIS

1. THE TAKE-OFF - In view of the flaps up take-off test conducted and the flaps up take-off information received from the Field Engineering Trainer Group, NAA, Columbus, Ohio, this aircraft should have become airborne when the stick was brought back to the take-off attitude.

The board was unable to determine the cause for the failure of the aircraft to assume a take-off attitude beyond the possibility of a failure or malfunction in the elevator control system. The elevator hydraulic boost actuator is being sent to O & R, Pensacola for DIR. The hydraulic lines on this actuator cannot be hooked up backwards due to non-compatible fittings.

The control linkage in the cockpit areas was completely destroyed by the fire. The cause for the failure or malfunction of the elevator control system is therefore undetermined.

2. Procedures used.

- a. The pre-taxi check-off was performed while taxiing out, which was in violation of the squadron's operating procedures.

ORIGINAL

- b. The speed brakes not extending is reason enough for the pilot to down the aircraft for the following reasons:
- (1) The pilot did not know the reason the speed brakes would not extend.
 - (2) The speed brakes not extending could be a possible indication of a failure in the hydraulic system.
- c. The pilot started his roll for take-off without checking all of his engine instruments. The pilot should not have started a take-off roll with the oil pressure gauge indicating low oil pressure (70 lbs). Minimum pressure for 100% is 114 lbs. Starting the take-off roll prior to checking all the engine instruments is in violation of the squadron's operating procedures.
- d. The decision of the pilot to make a flaps up take-off on a 6000 foot runway was very unwise and in violation of the squadron's operating procedures. The position at which TAKE-OFF was initiated was approximately 500 feet from the take-off end of the runway, therefore, the runway available for use was 5,500 feet.
- (1) The take-off distance for flaps up, under the conditions this attempt was made was a maximum of 3000 feet. The minimum stopping distance from 115 kts is 2320 feet. This requires 5320 feet of runway for take-off and abort without hesitation or indecision on the part of the pilot.
 - (2) The take-off distance for flaps down under the conditions this attempt was made require a roll distance of 2300 feet and a lift off speed of 98 kts. The minimum stopping distance from 98 kts is 1720 feet. This requires 4020 feet for take-off and abort. This would leave 1480 feet of spare runway and if the abort had been done without hesitation, the aircraft could have come to a stop in the arresting gear, which is 1500 feet from the end of the runway. It is felt therefore that had a flaps down take-off been attempted, this accident could have been averted.
- e. Neither pilot had his oxygen mask on which is in violation of Training Squadron SEVEN Instruction 10127.1B which is quoted in part "All personnel will wear the following items of flight clothing while flying in the T2J-1 aircraft: f. Oxygen mask from take-off to landing".

The pilots not having their masks on and being on cold mikes, definitely added to the confusion during the take-off, when CAPT (b) (6) was unable to get LCDR SECKINGER's attention by clicking the intercom switch to "CALL" position.

ORIGINAL

All the above listed violations definitely added to the confusion of the take-off and possibly hindered the pilot from making the correct decision at the right time when the difficulty of not being able to raise the nose was encountered.

3. The ejection system.

- a. The ejection was through the canopy due to the fact that the gas line to the canopy actuator was not attached. This item is on the maintenance major check sheet and was signed off as having been CHECKED on this aircraft during the last check.
- b. The rear seat not separating from the pilot was due to the fact that the pivot pin in the striker bellcrank was missing at the time of ejection. There is evidence of wear in the striker bellcrank pivot pin hole indicating that the pivot pin had been installed at one time. Since there were no work orders issued requiring removal of this pivot pin, it is believed by the board, that this pin was not properly secured by a cotter pin at the time of installation or it was removed and reinstalled insecurely or not reinstalled at all without a work order being issued. All other seats of this squadron were inspected for missing pivot pins and all pivot pins were found in and properly secured. The maintenance inspection check sheet lists the aneroid area as a check item, but does not spell out the items in this area, one of which is the anchor pin for the striker bellcrank. ©
- c. Front seat. Everything in this seat system functioned as designed. It could not be determined as to how the "D" ring was pulled, but the initiators were fired. The pilot states he only pulled the curtain.
- d. Oxygen masks.
 - a. Neither pilot had his oxygen mask on completely. They were hanging by one Hardiman fitting from the helmet.
 - b. The bailout bottle lasts from 2 to 3 minutes after ejection. CAPT (b) (6) was knocked unconscious when he hit the fence and by the time assistance arrived, it is believed he would have suffocated, had he had his mask on correctly. Since ground level ejections can end in rough terrain and the pilot can be injured there is a need for automatic release of the mask or some automatic device to let outside air into the system when the bailout bottle is empty after ejection.

PART IX COMMENTS

1. The primary contributing cause factor in this accident is the fact that the aircraft did not become airborne due to a suspected failure or malfunction of the elevator control system.

ORIGINAL

2. The contributing pilot cause factor in this accident is that a flaps up take-off was attempted, which required almost the full length of the runway for take-off roll and abort stopping distance. This same take-off attempt with flaps down left 1500 feet of runway remaining after take-off roll and abort stopping distance.
3. This take-off should never have been attempted for the following reasons:
 - a. Both pilots were Assistant Maintenance Officers and should have realized the significance of taking an aircraft that had discrepancies.
 - b. The low oil pressure would have been noted prior to commencing take-off roll had the correct procedure of checking engine instruments been used.
 - c. The speed brakes ^{would} not extend.
4. The procedure of going over check-off lists while taxiing on any type of flight is in violation of standard operating procedures of this squadron.

PART X RECOMMENDATIONS

1. It is recommended that closer attention by supervisory authority be exercised both in adherence to Standard Operating procedures and in review of maintenance procedures. A continuous review of procedures by all personnel, flight and maintenance, must be examined periodically in an effort to remain cognizant of changes required or occurrences of non-compliance with standard operating procedures and/or check sheets.
2. It is recommended that both the intermediate and major check sheets on the maintenance of the ejection seats be revised so that the check sheet shows each item to be checked, especially the striker arm pivot pin, which is not listed on the check sheet. It is further recommended that no work be accomplished on the ejection system without a work order being issued.
3. It is recommended that only qualified personnel be permitted to sign off gripes on/or inspection of the ejection seat system. If the number of qualified personnel assigned do not meet the requirements of the command, then a strenuous conscientious effort must be exerted to train enough other personnel to meet the needs. Special attention must be given to selecting only the most highly qualified personnel to be used as instructors.
4. It is believed that had CAPT (b) (6) been wearing his oxygen mask at the time of his low level ejection, he would have died from suffocation. This belief is based on the figures of usable time/quantity of the bailout bottle, which is activated at ejection. The emergency oxygen supply is capable of providing approximately 2 to 3 minutes of normal breathing at sea level. From the time of initiation of ejection until help arrived for CAPT (b) (6), 5 to 6 minutes has elapsed and CAPT (b) (6) was unconscious from the time he contacted the ground.

ORIGINAL

In view of the above it is recommended that the Bureau of Weapons immediately initiate a study of the problem, which is to insure that outside air be made available to the pilot as soon as the emergency oxygen supply has been depleted.

11

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

23

ORIGINAL

STATEMENT of CAPT (b) (6) USMC - PILOT

I signed out for T2J-1, BUNO 148222 about 0730S on 25 May 1961 with LCDR SECKINGER as dual pilot. We both did a complete pre-flight on the aircraft and there were no discrepancies noted. I went over the pre-start check-off list and started the aircraft. The start was normal.

I performed the pre-taxi check-off list while taxiing out and noted my speed brakes would not extend. Mr. SECKINGER and I made an intercom check and it was working normal.

The pre-take-off check list was completed and I put my flaps up for a flaps up take-off. I taxied out for take-off as I closed the canopy and locked my shoulder harness. When I got to 100%, I started rolling immediately.

Mr. SECKINGER and I were on cold mike and did not have our masks on. I noted as I was rolling the oil pressure was low. I noticed light vaporization in the pressurization intake and an unusual smell in the cockpit. The cockpit temperature was set on one. I kept clicking the mike trying to get Mr. SECKINGER's attention and he just looked at me in the mirror, not realizing I was trying to get him. The intercom had checked out okay in the line. Right after this, I heard him on the mike, but I did not understand what he said. At 100 kts, I tried to raise the nose to a take-off attitude, but it wouldn't come up. I reached an air-speed of about 110 to 115 knots and the nose still wouldn't come up. I could move the stick back, but it felt unusual. The nose did not assume take-off attitude. I didn't want to take-off, if it was going to be that hard to get off the ground, so I aborted. I took power off to idle and cut some of the switches and put my feet on the brakes, but I did not slow up. Then I reached for the hook and saw that I was past the barrier. Then I pulled back on the stick to get more braking action and I started to lift the gear handle. I thought if I could get the gear up, I could stop it, but there was no over run, so I decided to eject. I ejected right on the end of the runway. I estimate I was going about 60 knots. I had ejection control in the front cockpit. I ejected with the curtain and I believe LCDR SECKINGER went way ahead of me. The next thing I knew, I was going head first above the ground. I did not feel the parachute open. I remember looking back and seeing the risers as I landed on the fence and trees.

This accident could have been prevented if I had aborted the take-off earlier.



(b) (6)

CAPT USMC

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ENCLOSURE 1A

ORIGINAL

25 May 1961

Statement of CAPT. (b) (6) directly following crash as heard by
LT. (b) (6)

CAPT (b) (6) stated we taxied out to the runway, I was in the front cockpit. We pulled out on the runway, my speedbrakes were in and my flaps were up. I applied power for take-off and I noticed the oil pressure was low. I started to roll.

LCDR (b) (6) then interrupted with the question. "You took off with your flaps up?"

CAPT (b) (6) answered, "Yes, I wanted to do it the way, I was going to make a left turn out."

CAPT (b) (6) continued his statement. We were going down the runway, plane wasn't going to fly, speed brakes wouldn't work, brakes wouldn't work worth a damn, can't stop, I ejected.

This statement was heard approximately ten minutes after the crash, at the location where CAPT (b) (6) came down. CAPT (b) (6) regained consciousness at that time; he had not received any sedation, and considering his condition spoke very legibly and distinctly. He did not seem to be in great pain and was completely aware of what had happened.

(b) (6)

ENCLOSURE 1B

RESUME OF CAPT

(b) (6)

ORIGINAL
FLYING EXPERIENCE

COMMAND	TIME AND TYPE FLYING	TYPE A/C	HOURS FLOWN
VMF-115	AUG 55-FEB 57 VF	F4D-1 F4D-6 AD-5 T-28B SNB-5 TV-2	50 4 3 5 2 27
MARAVNRCPLBN AIRFMFPAC	MAR 57-APR 57 PROFICIENCY	TV-2	2
H & S FMF CAMP LEJUNE	MAY 57-FEB 59 PROFICIENCY	SNB TV-2 F9F-8	114 70 41
H & S 8TH MAR 2ND MAR DIV	FEB 59-JUNE 59 PROFICIENCY	SNB-5 F28B	23 4
VT-7	JULY 59-MAY 61 FLIGHT INSTRUCTOR	T2V-1 T-28B SNB-5 T2J-1	114 221 34 331

(b) (6)

LCDR USN
SAFETY OFFICER

ENCLOSURE 2A

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ORIGINAL

RESUME OF LCDR SECKINGER'S FLYING EXPERIENCE

COMMAND	TIME AND TYPE FLYING	TYPE A/C	HOURS FLOWN
VT-94	OCT 44-NOV 45 VT	TBM	442
CASU-22	DEC 45-MAR 46 PROFICIENCY	TBM SNB	22 10
VRF-3	MAR 46-MAY 46 VR FERRY	TBM R4D	18 36
VR-6	MAY 46-JUNE 47 VR	R5D SNJ	770 25
VF-98 (RESERVE SQUAD) INACTIVE DUTY	JUNE 47-JUNE 48 PROFICIENCY	FLU AD TBM	42 90 45
FASRON-1	JUNE 48-NOV 49 PROFICIENCY	F6F SNB	32 113
INACTIVE DUTY	NOV 49-JAN 51	NO FLYING	
NAS COLUMBUS	JAN 51-MAR 54 VR AND PROFICIENCY	SNJ SNB F6F FLU F2H TV-12 R4D R5D	38 318 115 31 68 37 173 138
NAS SEATTLE	MAR 54-OCT 55 VR AND PROFICIENCY	SNB R5D	42 334
CIC NAS GLENVIEW	NOV 55-FEB 56 TRAINING	SNB	37
TACRON 23	FEB 56-JULY 56 VR AND PROFICIENCY	SNB	75
FLIGHT TRO CEN NORFOLK	JULY 56-APR 58 PROFICIENCY	SNB	173
VF(AW) 4	APR 58-AUG 59 VF	TV-2 F2H SNB	30 113 40
VT-7	SEPT 59-MAY 61 TEST AND PROFICIENCY	SNB T2V	158 46

(b) (6)

ENCLOSURE 2B

LCDR USN
SAFETY OFFICER

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ORIGINAL

STATEMENT OF ENS (b) (6) USNR - STUDENT PILOT

At the time of the accident, I was in the control tower. I had a very clear view of the accident. The aircraft was cleared for take off on runway 17. It was the first plane to be cleared on runway 17, since the duty runway had been 13 just prior to the accident.

The winds were from 130-150/8, the alt. 29.86. The aircraft started it's normal take-off roll. As I watched the plane gain speed down the runway, I noticed that it was unusually fast for not being airborne.

As the plane passed the arresting gear, I knew something was definitely wrong and since the plane had not even assumed the take-off attitude. I then saw the nose oleo compress as the brakes were applied, but much too late to stop the plane.

The two pilots ejected just prior to leaving the runway. The seats did not appear to go higher than 50-75 feet. The plane left the runway and exploded. One of the parachutes streamed, but did not open. The other did not appear to even stream.

I am a flight student in Basic Training. I am in Formation stage of Training.

(b) (6)

ENS USNR

THIS IS CONSIDERED TO BE A CREDITABLE STATEMENT

ENCLOSURE 3A

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ORIGINAL

STATEMENT OF (b) (6) ACC - CHIEF TOWER OPERATOR

At 1448Z - VJ48222, GREY OAK 177 T2J was cleared for take-off on runway 17 South Field. His take off roll seemed normal, with sufficient airspeed to get airborne, after he passed the arresting gear, it looked as though he was trying to abort his take off. I realized he could not possibly stop in time and that he would drop off the end of the runway, so I yelled for (b) (6) AC1 to ring the crash phone. The A/C went off the end of the runway and burst into flames. I saw one parachute open partially and did not see the other one.

Kingsville 10MB5 was on the hardstand and was on the scene with Kings 17 ambulance at 1449, about one minute later. Kingsville 12MB5 at the base of South Tower was on the scene at 1451Z. The Helicopter was on the scene at 1452Z.

The weather at the time was 1400 broken 9000 broken higher broken, vis 10, temperature 84, Dew pt. 74, Wind SSW 7, ALT 29.85, Relative Humidity 73%.

My experience as a tower operator is as follows:

1. 9 yrs. tower
2. 3 yrs. GCA, and have attended Class A, B, and C AC Schools.

(b) (6)

ACC USN

THIS IS CONSIDERED TO BE A CREDITABLE STATEMENT

ENCLOSURE 3B

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ORIGINAL

STATEMENT OF (b) (6) AC1 - TOWER OPERATOR

VJ48222 T2J was taking off on runway 17, and was passing the gear. The aircraft appeared to make an attempt to abort. As the aircraft passed the intersection of taxiway E, the crash phone was activated. Both ejection seats left the aircraft as it passed the roll off end of the runway. The seats appeared to go up about 570 feet. The aircraft went off the roll end of the runway and burst into flame as it went down into the gully. As I looked up from the crash phone, I saw 2 MB5s, an ambulance and crash pickup proceeding down runway 17 to the scene.

Weather at the time of the crash was 1400 broken 9000 broken higher broken, visibility 10, temperature 84, dew point 74, SSW 7, altimeter 29.85, Relative Humidity 73%.

I have the following experience in air traffic control:

1. 7 years, 9 mo. total experience.
2. 1 year, 6 mo, radar controller.
3. 6 years, 3 mo. tower controller.

(b) (6)

AC1 USN

THIS IS CONSIDERED TO BE A CREDITABLE STATEMENT

ENCLOSURE 3C

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 7C OPMAVIST 3750.6D

ORIGINAL

MAINTENANCE OFFICER'S STATEMENT CONCERNING T2J-1, BUONO 148222 PILOT (b) (6)

T2J-1 BuNo 148222 was accepted new by VT-7 on 13 January 1961. A special inspection in accordance with CNATRA Instruction 3110.2 dated 10 October 1958 was performed. Since this inspection the aircraft has undergone the following periodic inspections.

Intermediate - 12 Feb 1961

1st Major - 15 Mar 1961

Intermediate - 18 Apr 1961

It was discovered on 14 May 1961 that this aircraft had a cracked fuselage frame upon commencement of the 2nd Major inspection. This inspection was terminated and the aircraft was prepared for a one-time flyaway to O&R at NAS Pensacola. It had ~~4.4~~ hours remaining to complete the ferry flight with 60.6 hours flown since last inspection.

T2J-1 BuNo 148222 accumulated 245.4 hours between ~~13 January 1961~~ *acceptance* and 25 May 1961. The history of this aircraft shows no discrepancies related to the accident. It had no record of elevator control malfunction.

T2J BuNo 148222 was transferred from A-3 to H-6 status on 15 May 1961 awaiting transfer to Pensacola. The aircraft had a routine daily and pre-flight inspection on 25 May 1961 prior to departing on the flight.

The following components were removed and emergency DIR is being conducted by NAS Pensacola O&R.

1. Fuel Control
2. Fuel Pump
3. Elevator Boost Package

Results of the DIR, if appropriate, will be forwarded as an addendum to this report.

The aircraft engine was disassembled and inspected by VT-7 under supervision of the PRATT & WHITNEY Factory representative. No indications of engine malfunction were noted.

(b) (6)

ICDR USN

ENCLOSURE (4)

JUN 1961

A complete review of all work orders and yellow sheets reveal no discrepancies which would require the seats of T2J-1 BUNO 1148222 to be pulled with the exception of the first major inspection completed on 15 March 1961. In addition there were no work orders or yellow sheet squawks which would require disconnection of the high pressure gas line to the canopy. This item is also spelled out as a check to be accomplished on major inspections. From the above, the following can be concluded:

1. The only time the seat was removed from the aircraft or worked on was during the first major inspection.
2. The high pressure gas lines to the canopy jettisoning device were signed off as being secure, reference item 1 of the Safety and Survival section of HIR.

As for specific inspection requirements of the seat the following is true:

1. Item 4m of the Safety and Survival section of the HIR calls for inspection of the aneroid mounting, arming pin, and thruster rod for security. This does not spell out an inspection of the bell crank or bell crank pivot pin. However, with the seat removed it is felt that any outward irregularity in this area would have been noted. Records indicate that the following men worked on the entire Safety and Survival section of the first major inspection of this aircraft in the following capacity:

(b) (6)	AA	Performed Work
(b) (6)	AME3	Systems Inspector

Records available in the Enlisted Personnel Office indicate (b) (6) was assigned to the Airframes Division of the Maintenance Department. Records are very limited as to (b) (6) qualifications. These qualifications can only be obtained from personnel previously detached. However, (b) (6) recalls (b) (6) on-the-job training and states he was well trained and was well qualified.

(b) (6) attended and graduated from AME(A) School. On 19 April 1961 was given an examination for Oxygen System Inspector in T2J-1 aircraft. A grade of 3.64 was attained. His nomination was signed by (b) (6) and approved by the Commanding Officer.

(b) (6) performed the only inspection accomplished on the rear ejection seat, and canopy system. (b) (6) signed off the first major inspection as a complete Safety and Survival Systems Inspector when he had only been designated as an Oxygen Systems Inspector. However, all indications from squadron personnel in a supervisory capacity claim (b) (6) to be qualified and trained to perform this work even though present procedures to designate him as such had not been accomplished.

Sixty hours subsequent to the first major inspection where the seat was pulled for the only time a second intermediate inspection was completed on 18 April 1961. The Safety and Survival section of this inspection was performed as follows:

ORIGINAL

(b) (6)

(b) (6)

AMS2
AMS2

Performed Work
Systems Inspector

The qualifications of these persons follow:

(b) (6)

AMS2

Reported aboard 24 May 1959 AMSAA
Designated 16 Dec 1959 AMS3
Designated 16 Nov 1960 AMS2

Schools attended: A/P Graduated 49 in class of 92 23 Jan 1959
AMS(A) Graduated 14 in class of 20 17 Apr 1959
NAMO TRA DET T2J-1 (A/F) Jul 1959
Systems Inspector: T2V-1 Oxygen system. Score 3.5
Designated 22 Jan 1960
Started working in AME Shop in October 1960

(b) (6)

AM2

Reported aboard 31 Oct 1958 AMSAA
Designated 16 Jan 1959 AMS3
Designated 16 May 1960 AMS2

Schools attended: A/P Graduated 53 in class of 143 18 Jul 1958
AMS(A) Graduated 13 in class of 31 Oct 1958
NAMO TRA DET T2J-1 (A/F) Jul 1960
Systems Inspector: T2J Airframes systems exam.
Score 3.5 Designated 22 Jan 1960
Started working in AME Shop in November 1960.

Item 2 (e) of the Safety and Survival section of the Intermediate Inspection calls for an inspection of the aneroid mount, arming pin and thruster rod for security. This area encompasses the bell crank which had the missing pivot pin. Both the person performing the work and the person performing the inspection are confident that the pin was installed at the time of this inspection.

Both (b) (6) and (b) (6) are considered highly qualified and conscientiously performed this inspection.

It is the Maintenance Officer's opinion that the missing bell crank pivot pin was installed at the factory with the cotter key end facing inward and was at least partially in the bell crank pivot point at the time of the first major and the second intermediate inspection. Had it not been in, it is felt that an obvious misalignment of the bell crank would have been noted.

Indentations and red paint from the washers indicate that a pin had been installed at one time and that a cotter key was used, although not necessarily bent for security. In view of the above it is felt that most probably the pin backed out of its retainer during the last 60.5 hours of flight because of constant insertion and removal of the safety pin.

There is nothing factual from available records that would lead to an answer as to why the gas line was disconnected. It was required to be inspected only during the first major. (b) (6) had signed the work order as having performed the work and (b) (6) had signed as Systems Inspector

ORIGINAL

ORIGINAL

for the work. (b) (6) cannot remember this aircraft but states that he is familiar with the importance of this particular inspection, and actually makes the inspection when he is acting as Systems Inspector. However, records do not indicate any work done in the gas line after the inspection by (b) (6) and (b) (6). It must be concluded that the line was disconnected at the time of the check but was not noted by either (b) (6) or (b) (6).

(b) (6)

ORIGINAL

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70 OPNAVINST 3750.50

AIRCRAFT FIRE/RESCUE REPORT
NAVJAG FORM 11135-1 (8-60)
 STATION AND LOCATION

NO TRANSMITTAL LETTER REQUIRED

REPORT SYMBOL BUVEPS 11135-1

U. S. Naval Auxiliary Air Station
Kingsville, Texas

ORIGINAL

DATE OF REPORT

26 May 1961

AFRIS NO.

10-61

DATE AND TIME OF INCIDENT

25 May 1961

0849

ON STATION

☒

OFF STATION

☐

REPORTING CUSTODIAN

VT-7

MODEL AIRCRAFT INVOLVED

T-2-J

BUREAU NO.

148222

TO: Chief, Bureau of Naval Weapons (SEEO)

EXACT LOCATION OF INCIDENT

**300 yards south of roll-off
 end of runway 17 at South
 Field.**

VIA MILITARY COMMAND

Chief of Naval Air Advanced Training Command

SIGNATURE

TYPE OF INCIDENT

TAKE-OFF	<input checked="" type="checkbox"/> LINE OR LOADING	FUELING
LANDING	<input type="checkbox"/> PARKED	MAINTENANCE
TAXIING	<input type="checkbox"/> DEFUELING	INFLIGHT

FIRE INVOLVED

YES	<input checked="" type="checkbox"/>
NO	<input type="checkbox"/>
IMPACT IGNITION	<input checked="" type="checkbox"/>
DELAYED IGNITION	<input type="checkbox"/>

ESTIMATED CASE

To be determined by AAR Board

OTHER (Specify)

CONDITIONS AT TIME OF INCIDENT

GENERAL WEATHER PICTURE

**High broken, 10 mile
 visibility**

WIND DIRECTION

South Southwest

WIND VELOCITY (mph)

7 knots

TEMPERATURE (°F)

84°

NATURE OF TERRAIN AT AND IN APPROACH TO INCIDENT

Rough Terrain

LIQUID FUEL QUANTITY

ESTIMATED ON BOARD BEFORE INCIDENT (lbs) **3781**

ESTIMATED ON BOARD AFTER INCIDENT (lbs) **None**

ESTIMATED SPILL AREA (Size in feet)

OTHER FUELS

None

PERSONNEL RESCUE

NO. PERSONNEL ON BOARD AIRCRAFT

2

DESCRIBE RESCUE METHODS USED

NO. PERSONNEL SURVIVED

1

None required

NO. PERSONNEL ESCAPED UNAIDED

1

NO. PERSONNEL RESCUED

0

FIRE FIGHTING

FIRST METHOD OF ALARM USED

TWO-WAY RADIO

EMERGENCY INTER-COM.

☒ EMERGENCY PHONE

TIME RECORD

TIME ALARM RECEIVED

0849

OTHER METHOD (State)

TIME EQUIPMENT ARRIVED

0850

STATION EQUIPMENT

EACH EQUIPMENT
 AVAILABLE AT INCIDENT

NO. PERSONNEL
 MANNING EQUIPMENT

QUANTITY EXTINGUISHING AGENTS USED

TYPE NO. LOADS USED

MIL.

CIV.

FOAM
 (gals. conc. used)

OTHER TYPES AND QUANTITIES

SEE ENCLOSURE (1)

STATION EQUIPMENT OUT OF SERVICE

TYPE

DEFICIENCY

NO. OF DAYS

EXPLAIN DELAYS TO REPAIR

MS-1

71-00524

Complete Motor Overhaul

281

Funds received 5-25-61 for repairs

MS-1

71-00822

Automatic Choke & Fuel Leak

1

In process

MS-1

71-00877

Oil Leak - Main Engine

2

In process

Tank Rusted Out

96-1904

Tank Rusted Out

59

Waiting on instructions for disposition

**SPECIAL HANDLING REQUIRED IN ACCORDANCE
 WITH PARA 70 OPNAVINST 3750.6D
 ENCLOSURE (7)**

DESCRIPTION OF DIFFICULTIES IN FIRE CONTROL AND
EXTINGUISHMENT DUE TO UNUSUAL CONDITIONS OR EQUIPMENT
AND/OR AGENT INADEQUACIES

Difficulty was encountered in reaching the crash site due to heavy undergrowth brush and rough eroded condition of terrain. Aircraft landed in washed out gully approximately twenty feet wide and fifteen feet deep.

RECOMMENDATIONS FOR IMPROVEMENTS IN EQUIPMENT
AND/OR PROCEDURES TO INCREASE EFFICIENCY

NONE


Orig & 1 SERQ Via
CNAVANTRA
CNATRA
AAR BOARD (VT-7)
CENTRAL FILES
CRASH OFFICER
OPERATIONS OFFICER

To be determined by AAR Board		MONETARY LOSSES To be determined by AAR Board		LOSS TO SURVIVING PROPERTY
PERCENT DAMAGE BY IMPACT	PERCENT DAMAGE BY FIRE	PERCENT DAMAGE BY FIRE	PERCENT DAMAGE BY FIRE	LOSS TO SURVIVING PROPERTY
mined by AAR Board	mined by AAR Board	mined by AAR Board	mined by AAR Board	NONE
DATE	PREPARED BY (Name and title)	SIGNATURE		
25 May 61	(b) (6) Crash Capt. GS-6			
DATE	STATION COMMANDING OFFICER	SIGNATURE		
31 MAY 1961	C. W. HARBERT CAPT USN C. WHANDLER OFFICER			
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70 OF NAVINST 8700.02				

DIAGRAM OF INCIDENT SHOWING WIND, DIRECTION, APPROACH OF
EQUIPMENT, POSITION OF AIRCRAFT, DISTANCES, ETC.
(Maps and photographs should be included, if significant)

ORIGINAL

NORTH



WIND SSW 7 KNOTS



(1286)
K-10

78 PAGES

125 PAGES

(X) #1 PILOT

WASH OUT

(X) #2 PILOT

(1036)
K-12

(122)
K-3

(510)
K-6

(431)
K-2

(158)
K-5

ROAD

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OPNAVINST 3750.6D

ENCLOSURE [7]

At 0849, 25 May 1961, the intercommunication and the crash circuit were activated by South Field Tower to report that a plane had crashed off of the roll-off end of runway 17 at South Field.

MB-5 #71-01286 was on the hardstand observing airfield operations. Aircraft number 148222 was observed rolling off runway 17 at high speed. Crew on the truck also noticed what appeared to be two ejection seats leaving the aircraft. MB-5 #71-01286 responded immediately toward aircraft and reached crash area at approximately 0850. The truck made setup position southeast of aircraft due to extremely precipitous terrain conditions and extinguishing procedures were started immediately.

MB-5 #71-01036 arrived at crash scene at approximately 0851. The Crash Captain and crew from MB-5 #71-01286 immediately located both pilots of aircraft. Pilot #1 was located approximately 78 paces southwest of aircraft; Pilot #2 was located approximately 125 paces south of aircraft. Number 1 was fatally injured. Pilot #2 was seriously injured and administered to by the Medical Officer at the scene.

Approximately 2 1/2 minutes elapsed when Fire Chief's pickup #94-31131, Assistant Fire Chief's pickup #94-29122, and Structural pumpers #73-01144 and #73-01154 arrived at the scene. Both Structural pumpers setup positions northeast of aircraft and assisted crash crew. Final extinguishment was accomplished at approximately 0916.

After fire was extinguished all equipment, except MB-5 #71-01036, was secured from emergency. MB-5 #71-01036 stoodby while investigating officers at crash scene investigated.

Extreme difficulty was encountered in reaching aircraft due to heavy brush and large washouts around aircraft and on base road.

STATION EQUIPMENT

EACH EQUIPMENT AVAILABLE AT INCIDENT		NO. PERSONNEL MANNING EQUIPMENT		QUANTITY EXTINGUISHING AGENTS USED	
TYPE	NO. LOADS USED	MIL.	CIV.	FOAM (gals. conc. used)	OTHER TYPES AND QUANTITIES
Pickup			1	None	None
Pickup			1	None	None
Power Wagon		1	1	None	None
Power Wagon			1	None	None
MB-5	1	1		20 gallons of foam	600 gallons of water
MB-5		5			200 gallons of water
MB-1		5		None	None
Pumper (7500PH)			5	None	None
Pumper (7500PH)			5	None	None

ORIGINAL

Enclosure (1)

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARA 70 OF NAVINST 3750.6D
ENCLOSURE (1)

[illegible]

1. OVERHAUL ACTIVITY NAS Pensacola		2. REPORT NO. 908	3. DATE 6-12-61	4. ASSEMBLY NOMENCLATURE Fuel Pump	
5. ASSEMBLY MOD 100T-901	6. ASSEMBLY SER 408	7. WFR'S CODE 97200	8. DATE REMOVED 5-29-61	9. ENGINE MOD J34-HE-48	10. ENGINE SER WE 220690
11. TOTAL HOURS 251.4	12. HOURS SINCE LAST O/H None	13. DATE LAST O/H ---	14. LAST OVERHAUL ACTIVITY ---		15. NO. PREV. O/H'S 0
16. REASON FOR REMOVAL AND CODE Accident Damage 4B		17. OPERATING ACTIVITY VT-7	18. WFFUR/AAR/FLIDA SER 899	19. AC/MISSILE MOD T2J-1	20. AC/MISSILE SUNO 148222
24. DESCRIPTION OF FINDINGS (Include name of Primary Part Failure) [CODE BUNEPFLASUPREP CEN NSG 021946Z of June 1961 refers				21. PRIMARY PART FAILURE COND.	
1. Disassembly inspection revealed serious heat damage on all external and internal parts.				NO.	
2. No indication of malfunction or material failure was found.				22. PARTS REMOVED COND.	
COPY TO: BUNEPFLASUPREP CEN (FRAE-4) BUNEPFLASUPREP CEN (RAFF-2) NAVAVSAPCEN BUNEPFLASUPREP CEN EAST HARTFORD CHABRA CHABATRA				23. APPLICABLE RLS., CHGS., ETC., INCORPORATED	
25. CONCLUSIONS (Para. Nos. correspond to paragraph numbers under Findings) 1. Resulted from fire after accident.				NUMBER YES NO	
26. RECOMMENDATIONS [CODE None				27. SIGNATURE (b) (6)	
28. TITLE Aero. Engr. Supt.				29. DATE 6-13-61	

DISASSEMBLY AND INSPECTION REPORT NAVAER-2901 (REV. 12-58)

U.S. GOVERNMENT PRINTING OFFICE: 1960 O-547117

1. OVERHAUL ACTIVITY NAS Pensacola		2. REPORT NO. 909	3. DATE 6-12-61	4. ASSEMBLY NOMENCLATURE Fuel Control	
5. ASSEMBLY MOD 100T-932	6. ASSEMBLY SER 221410	7. WFR'S CODE 66903	8. DATE REMOVED 5-29-61	9. ENGINE MOD J34-HE-48	10. ENGINE SER WE220690
11. TOTAL HOURS 251.4	12. HOURS SINCE LAST O/H None	13. DATE LAST O/H ---	14. LAST OVERHAUL ACTIVITY ---		15. NO. PREV. O/H'S 0
16. REASON FOR REMOVAL AND CODE Accident Damage 4B		17. OPERATING ACTIVITY VT-7	18. WFFUR/AAR/FLIDA SER 860	19. AC/MISSILE MOD T2J-1	20. AC/MISSILE SUNO 148222
24. DESCRIPTION OF FINDINGS (Include name of Primary Part Failure) [CODE BUNEPFLASUPREP CEN NSG 021946Z of June 1961 refers				21. PRIMARY PART FAILURE COND.	
1. Disassembly inspection revealed serious heat damage on all external and internal parts.				NO.	
2. No indication of malfunction or material failure was found.				22. PARTS REMOVED COND.	
COPY TO: BUNEPFLASUPREP CEN (FRAE-4) BUNEPFLASUPREP CEN (RAFF-2) NAVAVSAPCEN BUNEPFLASUPREP CEN EAST HARTFORD CHABRA CHABATRA				23. APPLICABLE RLS., CHGS., ETC., INCORPORATED	
25. CONCLUSIONS (Para. Nos. correspond to paragraph numbers under Findings) 1. Resulted from fire after accident.				NUMBER YES NO	
26. RECOMMENDATIONS [CODE None				27. SIGNATURE (b) (6)	
28. TITLE Aero. Engr. Supt.				29. DATE 6-13-61	

DISASSEMBLY AND INSPECTION REPORT NAVAER-2901 (REV. 12-58)

U.S. GOVERNMENT PRINTING OFFICE: 1960 O-547117

SECTION A - IDENTIFICATION

1. YOUN (Name and mailing address of activity) VT-7 NAAS Kingsville, Texas										2. MOS NUMBER 6-52	
3. REPORT FILED BY (Name and Signature of Medical Officer) DATE (b) (6) LT MC USMC JUN 19 1961										4. FORWARDED (Name and Signature of Appointing Authority) DATE (b) (6) MC USMC	
5. TYPE OF MISAP <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT			6. TIME AND DATE 0818 S 25 May 1961		7. GEOGRAPHICAL LOCATION South Field, NAAS Kingsville, Texas						
8. MODEL A/C T2J-1		9. BUNO 116222		10. NO. OF OCCUPANTS 2		11. TYPE ACCT. 51		12. DAMAGE CODE A		13. UNIT OPERATING A/C VT-7 NAAS, Kingsville, Texas	
14. INDIVIDUALS INVOLVED - USE ADDITIONAL SHEETS IF REQUIRED. NAME (Last, first and middle initials)			15. UNIT TO WHICH ATTACHED			16. RANK, DATE		17. FILE/SERV. NO. DESIGNATOR		18. DILLET	
a. IN CONTROL OF A/C SMITH, (b) (6)			VT-7			CAPT		(b) (6)		Instructor USMC	
b. SECKINGER, Neil Vincent			VT-7			LCDR		(b) (6)		Asst. Maint. Officer USN	
c.											
d.											

22. CLARIFICATION OF ITEMS 15-22 WHEN NECESSARY

24. MODEL - OTHER A/C IF INVOLVED	25. BUNO	26. NO. OF OCCUPANTS	27. UNIT OPERATING A/C	28. DAMAGE CODE	29. REPORT NO.
-----------------------------------	----------	----------------------	------------------------	-----------------	----------------

30. DETAILED NARRATIVE ACCOUNT OF ACCIDENT (Use additional 8 X 10 1/2 plain sheets if required)

On 25 May 1961, CAPT (b) (6) signed out for T2J-1, bureau number 116222 with LCDR SECKINGER as dual pilot for a ferry flight from NAAS Kingsville, Texas to NAS PENSACOLA, FLORIDA.

The aircraft was pre-flighted by both pilots and no discrepancies were noted. The pilots strapped in with CAPT (b) (6) in the front cockpit and LCDR SECKINGER in the rear cockpit.

CAPT (b) (6) went over the pre-start check-off list and started the aircraft. The start was normal and CAPT (b) (6) went over his pre-taxi check-off list. He noted that the speed brakes did not extend when he pressed the switch to extend the speed brakes. The speed brakes indicator would show barber pole as he pressed the switch and then would immediately show in when he let go of the switch. A communications check on the intercommunications system was made and it worked normal. The oxygen masks were not fully put on by either pilot.

CAPT (b) (6) then taxied out to the duty runway completing his pre-take-off check-off list while taxiing except for the canopy and his shoulder harness.

(CONTINUED ON ATTACHED SHEET)

SECTION B - MEDICAL OFFICER'S QUESTIONNAIRE

YES	NO	DID THE FLIGHT SURGEON:		(If "NO" state reason in space below.)	
		1. VISIT THE SCENE OF THE MISAP?			
		2. PARTICIPATE FULLY IN THE FIELD INVESTIGATION?			
		3. PARTICIPATE FULLY IN THE DELIBERATIONS OF THE A/C ACCIDENT BOARD?			
4. APPROXIMATE NUMBER OF HOURS SPENT BY THE FLIGHT SURGEON:		5. IN FIELD INVESTIGATION		6. IN BOARD DELIBERATIONS	
7. REPORT PREPARATION CHECK LIST					
<input checked="" type="checkbox"/> ALL PARTS OF FORM COMPLETED		<input checked="" type="checkbox"/> SURVIVORS' NARRATIVES		<input checked="" type="checkbox"/> PHOTOS	
		<input checked="" type="checkbox"/> CONCLUSIONS AND RECOMMENDATIONS		<input checked="" type="checkbox"/> REQUIRED COPIES FURNISHED	

CAPT (b) (6) requested and received clearance for take-off. As he taxied into position for take-off, he closed the canopy and locked his shoulder harness and put the flaps up for a flaps up take-off.

CAPT (b) (6) applied full throttle control while holding his brakes and as soon as the engine tachometer indicated 1000 RPM, CAPT (b) (6) released the brakes and started the take-off roll.

CAPT (b) (6) noted the oil pressure was low (estimate 70 LBS pressure) and tried to tell LCDR SECKINGER in the rear cockpit about it. He held his oxygen mask over his face with his left hand as he pushed the intercom switch to "CALL" but was unable to get a response from LCDR SECKINGER. The other instruments indicated the engine was operating normally.

LCDR SECKINGER spoke on the intercom shortly after this, but CAPT (b) (6) did not understand what was said.

The take-off roll continued until 100 kts was reached and CAPT (b) (6) tried to raise the nose to take-off attitude. The nose would not come up even though an airspeed of 110 to 115 kts had been attained. CAPT (b) (6) tried a second time to raise the nose to take-off attitude, but to no avail.

When the nose did not come up on this second attempt, CAPT (b) (6) decided to abort the take-off. He reduced power to idle, turned off some switches and reached for the hook, but he saw he was past the runway arresting gear. He pulled the stick full back and applied full brake and saw he couldn't stop the aircraft before going off the end of the runway.

Inasmuch as there was no runway over-run, CAPT (b) (6) pulled the ejection curtain at the end of the runway. The ejection control was in the front cockpit and both pilots were ejected through the canopy.

CAPT (b) (6) section of the ejection system worked as it was designed to do, with the exception of the canopy. The distance from point of initiation to touchdown was 624 feet. LCDR SECKINGER went 599 feet from the end of the runway in the seat. Seat separation did not occur due to the fact that the striker air pivot clevis pin in the anroid linkage was missing.

The aircraft rolled off the end of the runway into a deep gully and came to rest 491 feet from the end of the runway. The aircraft caught fire immediately. The crash crew arrived on the scene shortly thereafter and took charge.

SECTION C - PHYSIOLOGICAL, HUMAN ENGINEERING, DESIGN, SOCIO-PSYCHOLOGICAL, AND TRAINING FACTORS WHICH CONTRIBUTED IN SOME DEGREE TO THIS A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT

NAME OF INDIVIDUAL (Last, first, middle)

(b) (6)

MODEL A/C

T2J-1

Check E-Established, S-Suspected, or P-Present for each factor selected. Additional 8X10 1/2 plain sheets will be used for the supporting account of items checked below. Identify each statement with the factor and section identification (e.g., C1, C2, etc.). Attach all sheets pertaining to these factors to this form upon completion.

E	S	P	✓ FACTORS	E	S	P	✓ FACTORS
			PHYSIOLOGICAL:				SOCIO-PSYCHOLOGICAL: (Emotional stress from duty sources)
			1. Physically incapacitated in flight				29. Expediting/Delays
			2. "G" forces				30. Weather
			3. Environmental stress - External				31. Mechanical Problems
			4. - Internal				32. Social and working relationships
			5. Dysbarism/explosive decompression				33. Personal comfort
			6. Diet				34. Regulations
			7. Fatigue				35. Facilities
			8. Hypoxia				36. Navigation
			9. Related illness				37. Duty assignment
			10. Vertigo/Disorientation/Illusions				38. Personality traits
			11. Hyperventilation				NON-STRESS FACTORS:
			12. Drugs				39. Faulty attention
			13. Physical state				40. Poor judgement (See Section E, Par.
			14. OTHER:				41. Forgetfulness 2a, 2b, 2c, 2d, 2e)
			HUMAN ENGINEERING AND DESIGN:				42. OTHER SOCIO-PSYCHOLOGICAL FACTORS
			15. Personal equipment				
			16. Displays and/or controls				
			17. Work arrangement				
			18. Working environment				
			19. Habit interference				TRAINING FACTORS:
			20. OTHER:				43. Physiological training
			SOCIO-PSYCHOLOGICAL: (Emotional stress from non-duty sources)				44. Emergency Procedures training
			21. Pregnancy				45. Survival and rescue training
			22. Illness or death				46. Refresher training
			23. Arguments				47. Transition training
			24. Elated/Depressed state				48. OTHER:
			25. Personal habits - Drinking				
			26. - Sex				
			27. - Gambling				
			28. - Debts				

SECTION D - AIR CREW DATA (fill in where applicable)

1. Flight time past 30 days	30.1	7. Total time in model	330.7
2. Flight time last 24 hours	3.0	8. Number of days grounded last month, give reason	
3. Number of flights in last 24 hours	2.0	9. Number of and dates of previous accidents	0
4. Time at controls this flight	0.1		
5. Number of hours duty last 24 hours	10.0		
6. Total flight time	1601.9		0

SECTION E - CONTRIBUTING FACTORS AND THEIR ANALYSES (As condensed from Part I, Section D and Part VIII of the AAR)

NOTE: Fill in this section only on that set of forms prepared for FIMT individual listed in Section A, i.e. 15(a). Attach additional sheets as necessary.

SEE ATTACHED SHEETS.

MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT—Page 2

OPNAV FORM 3750-8A (Rev. 5-58)

OPNAV REPORT 3750-7

SECTION C—PHYSIOLOGICAL, HUMAN ENGINEERING, DESIGN, SOCIO-PSYCHOLOGICAL, AND TRAINING FACTORS WHICH CONTRIBUTED IN SOME DEGREE TO THIS A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

SECKINGER, Neil Vincent

T2J-1

Check E—Established, S—Suspected, or P—Present for each factor selected. Additional 8X10½ plain sheets will be used for the supporting account of items checked below. Identify each statement with the factor and section identification (e.g., C1, C2, etc.). Attach all sheets pertaining to these factors to this form upon completion.

E	S	P	✓ FACTORS	E	S	P	✓ FACTORS
			PHYSIOLOGICAL:				SOCIO-PSYCHOLOGICAL: (Emotional stress from duty sources)
			1. Physically incapacitated in flight				29. Expeditings/Delays
			2. "G" forces				30. Weather
			3. Environmental stress - External				31. Mechanical Problems
			4. Internal				32. Social and working relationships
			5. Dysbarism/explosive decompression				33. Personal comfort
			6. Diet				34. Regulations
			7. Fatigue				35. Facilities
			8. Hypoxia				36. Navigation
			9. Related illness				37. Duty assignment
			10. Vertigo/Disorientation/Illusions				38. Personality traits
			11. Hyperventilation				NON-STRESS FACTORS:
			12. Drugs				39. Faulty attention
			13. Physical state				40. Poor judgement (See Section E, Par. 2a, 2b, 2c, 2d, 2e)
			14. OTHER:				41. Forgetfulness
			HUMAN ENGINEERING AND DESIGN:				42. OTHER SOCIO-PSYCHOLOGICAL FACTORS
			15. Personal equipment				
			16. Displays and/or controls				
			17. Work arrangement				
			18. Working environment				
			19. Habit interference				TRAINING FACTORS:
			20. OTHER:				43. Physiological training
			SOCIO-PSYCHOLOGICAL: (Emotional stress from non-duty sources)				44. Emergency Procedures training
			21. Pregnancy				45. Survival and rescue training
			22. Illness or death				46. Refresher training
			23. Arguments				47. Transition training
			24. Elated/Depressed state				48. OTHER:
			25. Personal habits - Drinking				
			26. Sex				
			27. Gambling				
			28. Debts				

SECTION D — AIR CREW DATA (fill in where applicable)

1. Flight time past 30 days	14.6	7. Total time in model	77.1
2. Flight time last 24 hours	0.0	8. Number of days grounded last month, give reason	
3. Number of flights in last 24 hours	0.0		0
4. Time at controls this flight	0.0	9. Number of and dates of previous accidents	
5. Number of hours duty last 24 hours	8.0		One accident (engine failure): 2 Nov 1944
6. Total flight time	1036.5		TW-1 FCLP

SECTION E — CONTRIBUTING FACTORS AND THEIR ANALYSIS (As condensed from Part I, Sect. D and Part VIII of the ARR)

NOTE: Fill in this section only on that set of forms prepared for FIRST individual listed in Section A, i.e. 15(a). Attach additional sheets as necessary.

SEE ATTACHED SHEETS.

1. THE TAKE-OFF - In view of the flaps up take-off test conducted and the flaps up take-off information received from the Field Engineering Trainer Group, NAA, Columbus, Ohio, this aircraft should have become airborne when the stick was brought back to the take-off attitude.

The board was unable to determine the cause for the failure of the aircraft to assume a take-off attitude beyond the possibility of a failure or malfunction in the elevator control system. The elevator hydraulic boost actuator is being sent to O & R, Pensacola for DIR. The hydraulic lines on this actuator cannot be hooked up backwards due to non-compatible fittings.

The control linkage in the cockpit areas was completely destroyed by the fire. The cause for the failure or malfunction of the elevator control system is therefore undetermined.

2. Procedures used.

- a. The pre-taxi check-off was performed while taxiing out, which was in violation of the squadron's operating procedures.
- b. The speed brakes not extending is reason enough for the pilot to down the aircraft for the following reasons:
 - (1) The pilot did not know the reason the speed brakes would not extend.
 - (2) The speed brakes not extending could be a possible indication of a failure in the hydraulic system.
- c. The pilot started his roll for take-off without checking all of his engine instruments. The pilot should not have started a take-off roll with the oil pressure gauge indicating low oil pressure (70 lbs). Minimum pressure for 100% is 114 lbs. Starting the take-off roll prior to checking all the engine instruments is in violation of the squadron's operating procedures.
- d. The decision of the pilot to make a flaps up take-off on a 6000 foot runway was very unwise and in violation of the squadron's operating procedures. The position at which TAKE-OFF was initiated was approximately 500 feet from the take-off end of the runway, therefore, the runway available for use was 5,500 feet.
 - (1) The take-off distance for flaps up, under the conditions this attempt was made was a maximum of 3000 feet. The minimum stopping distance from 115 kts is 2320 feet. This requires 5320 feet of runway for take-off and abort without hesitation or indecision on the part of the pilot.

(2) The take-off distance for flaps down under the conditions this attempt was made requires a roll distance of 2300 feet and a lift off speed of 98 kts. The minimum stopping distance from 98 kts is 1720 feet. This requires 4020 feet for take-off and abort. This would leave 1480 feet of spare runway and if the abort had been done without hesitation, the aircraft could have come to a stop in the arresting gear, which is 1500 feet from the end of the runway. It is felt therefore that had a flaps down take-off been attempted, this accident could have been averted.

- e. Neither pilot had his oxygen mask on which is in violation of Training Squadron SEVEN Instruction 10127.1B which is quoted in part "All personnel will wear the following items of flight clothing while flying in the T2J-1 aircraft: f. Oxygen mask from take-off to landing." (See enclosure 3A)

The pilots not having their masks on and being on cold mikes definitely added to the confusion during the take-off, when CAPT (b) (6) was unable to get LCDR SECKINGER's attention by clicking the intercom switch to "CALL" position.

All the above listed violations definitely added to the confusion of the take-off and possibly hindered the pilot from making the correct decision at the right time when the difficulty of not being able to raise the nose was encountered.

3. The ejection system.

- a. The ejection was through the canopy due to the fact that the gas line to the canopy actuator was not attached. This item is on the maintenance major check sheet and was signed off as having been CHECKED on this aircraft during the last check.
- b. The rear seat not separating from the pilot was due to the fact that the pivot pin in the striker bellcrank was missing at the time of ejection (See encl. SN & SN). There is evidence of wear in the striker bellcrank pivot pin hole indicating that the pivot pin had been installed at one time. Since there were no work orders issued requiring removal of this pivot pin, it is believed by the board, that this pin was not properly secured by a cotter pin at the time of installation or it was removed and reinstalled insecurely or not reinstalled at all without a work order being issued. All other seats of this squadron were inspected for missing pivot pins and all pivot pins were found in and properly secured. The maintenance inspection check sheet lists the aneroid area as a check item, but does not spell out the items in this area, one of which is the anchor pin for the striker bellcrank.

- c. Front seat. Everything in this seat system functioned as designed. It could not be determined as to how the "D" ring was pulled, but the initiators were fired. The pilot states he only pulled the curtain.
- d. Oxygen masks.
 - (1) Neither pilot had his oxygen mask on completely. They were hanging by one Hardeman fitting from the helmet.
 - (2) The bailout bottle lasts from 2 to 3 minutes after ejection. CAPT (b) (6) was knocked unconscious when he hit the fence and by the time assistance arrived, it is believed he would have suffocated, had he had his mask on correctly. Since ground level ejections can end in rough terrain and the pilot can be injured there is a need for automatic release of the mask or some automatic device to let outside air into the system when the bailout bottle is empty after ejection.

SECTION F - SAFETY, PERSONAL, AND SURVIVAL EQUIPMENT
Prepare a narrative account of damaged or failed items. Identify each item discussed (e.g., F1, F2, etc.)

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

(b) (6)

T2J-1

GENERAL DESCRIPTION OF EQUIPMENT	AVAILABLE		SPECIFIC MODEL OR TYPE	UTILIZED		FAILED		DESCRIPTION OF DAMAGE TO EQUIPMENT
	YES	NO		YES	NO	YES	NO	
1. Shoulder harness	X		M-7 Par. Int. Harness	X		X		
2. Lap belt	X		Int. M/A 249-530-123	X		X		
3. Inertia reel	X		False-co Ballistic	X		X		
4. G-Suit		X	Not necessary					
5. Pressure suit-full or partial		X	Not necessary					
6. Exposure suit		X	Not necessary					
7. Flight suit (Other than above)	X		Summer Flying	X		X		
8. Helmet	X		Air Force P-4A	X		X		See Encl. 5I and 5J
9. Goggles/Eyeshield	X		Air Force P-4A	X		X		See Encl. 5I and 5J
10. Shoes	X		Boondockers	X		X		
11. Gloves	X		Summer Flight Gloves	X				Habitually not put on by this pilot until A/C is airborne.
12. Life vest		X	Not necessary					
13. Life raft	X		MK III		X			
14. OTHER:								
15. SIGNAL DEVICE - Flare (Night)	X		MK-13 MOD 0		X			
16. - Flare (Day)	X		MK-13 MOD 0		X			
17. - Dye marker	X		FSN 47-6850-285-8000	X				
18. - Radio		X	Not issued					
19. - Flashlight		X	Not necessary					
20. - Mirror	X		MK III		X			
21. OTHER:								
22. SURVIVAL GEAR - Knife		X	Survival					
23. - First aid kit	X		Kit, First Air Aeronautic (Utilized - no)					
24. - Shelter								
25. - Food								
26. OTHER:								
27. RESCUE - Vehicle	X		EM Ambulance	X		X		
28. - Sling, Net, Stretcher								
29. OTHER:								

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE

OXYGEN EQUIPMENT	1. MAKE - MODEL OR TYPE A13		2. MODIFICATIONS, IF ANY None	
	3. REGULATOR - MODEL OR TYPE Robertshaw-Fulton		4. MODIFICATIONS, IF ANY None	
	5. PREFLIGHTED BY USER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		6. IF NO, WHY NOT	
	7. LIST DISCREPANCIES NOTED BY PREFLIGHT CHECK None			
RELEASE DEVICES	8. OXYGEN SUPPLY: PRIOR TO FLIGHT: 4.5 LITERS (Liquid) _____ P.S.I. (Gas) TIME OF ACCIDENT: 4.5 LITERS (Liquid) _____ P.S.I. (Gas)		9. WAS OXYGEN IN USE AT TIME OF ACCIDENT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
	10. IF YES, WAS SELECTION SETTING <input type="checkbox"/> 100% <input type="checkbox"/> NORMAL		11. WAS ALL OXYGEN EQUIPMENT NECESSARY FOR THIS FLIGHT AVAILABLE? IF NO, LIST ITEMS AND REASON WHY. <input type="checkbox"/> YES <input type="checkbox"/> NO	
	12. WAS OXYGEN MASK REMOVED AT ANY TIME IN FLIGHT? IF YES, GIVE DURATION AND REASON. <input type="checkbox"/> NO <input type="checkbox"/> YES See attached sheet			
	13. TYPE CHUTE RELEASE DEVICE Parachute Release		14. TYPE HARNESS RELEASE DEVICE Integrated Harness	
	15. WHEN WERE RELEASE DEVICES ACTIVATED? Immediately after ejection			
	16. WERE DIFFICULTIES ENCOUNTERED WITH RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input type="checkbox"/> NO			
17. WERE DIFFICULTIES ENCOUNTERED AFTER ACTIVATING RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input type="checkbox"/> NO				
18. WAS LIFE VEST INFLATED PRIOR TO ACTIVATING RELEASE DEVICES? IF YES, WHAT DIFFICULTIES DID THIS PRODUCE? <input type="checkbox"/> YES <input type="checkbox"/> NO				

G-12

Neither pilot had his oxygen mask on which is in violation of Training Squadron SEVEN Instruction 10127.1B which is quoted in part "All personnel will wear the following items of flight clothing while flying in the T2J-1 aircraft: f. Oxygen mask from take-off to landing." (See encl. 3A). CAPT (b) (6) could give no explanation for not utilizing his oxygen equipment.

SECTION F - SAFETY, PERSONAL, AND SURVIVAL EQUIPMENT

Prepare a narrative account of damaged or failed items. Identify each item discussed (e.g., F1, F2, etc.)

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

SECKINGER, Neil Vincent

T21-1

GENERAL DESCRIPTION OF EQUIPMENT	AVAILABLE		SPECIFIC MODEL OR TYPE	UTILIZED		FAILED		DESCRIPTION OF DAMAGE TO EQUIPMENT
	YES	NO		YES	NO	YES	NO	
1. Shoulder harness	<input checked="" type="checkbox"/>		NR-7 Par. Int. Harness	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
2. Lap belt	<input checked="" type="checkbox"/>		Int. M/A 249-530-121	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
3. Inertia reel	<input checked="" type="checkbox"/>		Falco-co Ballistic	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
4. G-Suit		<input checked="" type="checkbox"/>	Not necessary					
5. Pressure suit-full or partial		<input checked="" type="checkbox"/>	Not necessary					
6. Exposure suit		<input checked="" type="checkbox"/>	Not necessary					
7. Flight suit (Other than above)	<input checked="" type="checkbox"/>		Summer Flying	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	Scattered tears
8. Helmet	<input checked="" type="checkbox"/>		AFH-5	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	See encl. 5-0 and 5P
9. Goggles/Eyeshield	<input checked="" type="checkbox"/>		AFH-5	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	See encl. 5-0 and 5P
10. Shoes	<input checked="" type="checkbox"/>		Boondockers	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
11. Gloves	<input checked="" type="checkbox"/>		Summer Flight Gloves	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
12. Life vest		<input checked="" type="checkbox"/>	Not necessary					
13. Life raft	<input checked="" type="checkbox"/>		MX III		<input checked="" type="checkbox"/>			
14. OTHER:								
15. SIGNAL DEVICE - Flare (Night)	<input checked="" type="checkbox"/>		MX-13 MGD 0		<input checked="" type="checkbox"/>			
16. - Flare (Day)	<input checked="" type="checkbox"/>		MX-13 MGD 0		<input checked="" type="checkbox"/>			
17. - Dye marker	<input checked="" type="checkbox"/>		FSM-WF-6850-285-8000	<input checked="" type="checkbox"/>				
18. - Radio		<input checked="" type="checkbox"/>	Not issued					
19. - Flashlight		<input checked="" type="checkbox"/>	Not necessary					
20. - Mirror	<input checked="" type="checkbox"/>		MX III		<input checked="" type="checkbox"/>			
21. OTHER:								
22. SURVIVAL GEAR - Knife		<input checked="" type="checkbox"/>	Survival					
23. - First aid kit	<input checked="" type="checkbox"/>		Kit, First Aid, Aeronautic (utilized - no)					
24. - Shelter								
25. - Food								
26. OTHER:								
27. RESCUE - Vehicle	<input checked="" type="checkbox"/>		IBM Ambulance	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	
28. - Sling, Net, Stretcher								
29. OTHER:								

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE

OXYGEN EQUIPMENT	1. MAKE - MODEL OR TYPE A33A	2. MODIFICATIONS, IF ANY None
	3. REGULATOR - MODEL OR TYPE Robertshaw-Fulton	4. MODIFICATIONS, IF ANY None
	5. PREFLIGHTED BY USER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	6. IF NO, WHY NOT
	7. LIST DISCREPANCIES NOTED BY PREFLIGHT CHECK	
OXYGEN EQUIPMENT	8. OXYGEN SUPPLY: 4.5 LITERS (Liquid) 4.5 P.S.I. (Gas) 4.5 LITERS (Liquid) 4.5 P.S.I. (Gas)	
	9. WAS OXYGEN IN USE AT TIME OF ACCIDENT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
	10. IF YES, WAS SELECTOR SETTING <input type="checkbox"/> 100% <input type="checkbox"/> NORMAL	
	11. WAS ALL OXYGEN EQUIPMENT NECESSARY FOR THIS FLIGHT AVAILABLE? IF NO, LIST ITEMS AND REASON WHY.	
	12. WAS OXYGEN MASK REMOVED AT ANY TIME IN FLIGHT? IF YES, GIVE DURATION AND REASON. <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES See attached sheet	
RELEASE DEVICES	13. TYPE CHUTE RELEASE DEVICE Parachute Release	14. TYPE PARACHUTE RELEASE DEVICE Tandem-4 Harness
	15. WHEN WERE RELEASE DEVICES ACTIVATED? Not activated	
	16. WERE DIFFICULTIES ENCOUNTERED WITH RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
	17. WERE DIFFICULTIES ENCOUNTERED AFTER ACTIVATING RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
RELEASE DEVICES	18. WAS LIFE VEST INFLATED PRIOR TO ACTIVATING RELEASE DEVICES? IF YES, WHAT DIFFICULTIES DID THIS PRODUCE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	

(Continued on OPNAV FORM 3750-8C)

G-12

Neither pilot had his oxygen mask on which is in violation of Training Squadron SEVEN Instruction 10127.1B which is quoted in part "All personnel will wear the following items of flight clothing while flying in the T2J-1 aircraft: f. Oxygen mask from take-off to landing." (See encl. 3A)

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE (Contd.)

NAME OF INDIVIDUAL (Last, first, middle)

(b) (6)

MODEL A/C

T2J-1

RESTRAINT HARNESS

19. INTEGRATED HARNESS SYSTEM, MODEL/TYPE

MB-7 Par. Torso Harness

20. INTEGRATED?

☒ FULL ☐ PARTIAL

21. MODIFICATIONS, IF ANY STATE REASON

Rocket Jet Connector Reversed

22. DID INTEGRATED HARNESS FIT PROPERLY? IF NO, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR

☐ NO ☒ YES

23. INTEGRATED HARNESS FITTING WAS CONDUCTED BY:

☐ WEARER ☐ FLIGHT SURGEON ☒ PARACHUTE RIGGER ☐ AVIATION EQUIPMENT OFFICER ☐ OTHER

24. IF SHOULDER HARNESS WAS USED, WAS IT:

☒ LOCKED ☐ UNLOCKED ☐ TIGHT ☐ SLACK ☐ OTHER CONDITION

HELMET

25. TYPE HELMET

Air Force P-1A

26. LIST PRESCRIBED MODIFICATIONS

Hardeman fittings

27. OTHER MODIFICATIONS AND REASON FOR THEM

28. DID HELMET FIT PROPERLY? IF NO, GIVE REASON

☒ YES ☐ NO

29. HELMET FITTING WAS CONDUCTED BY:

☐ WEARER ☐ FLIGHT SURGEON ☒ PARACHUTE RIGGER ☐ AVIATION EQUIPMENT OFFICER ☐ OTHER

30. TYPE CHUTE

MB-7

31. LAST PACKING DATE

27 March 61

32. MODEL/TYPE BAILOUT OXYGEN

P-151300-5

33. AUTOMATIC RIPCORD, IF INSTALLED (Model and type)

☐ NONE ☒ Master Specialty 1000-C

34. DID AUTOMATIC RIPCORD FAIL? IF YES, WHY?

☒ NO

35. WAS RIPCORD ACTIVATION

☐ MANUAL ☒ AUTOMATIC?

36. IF MANUALLY ACTIVATED STATE REASON AND ANY DIFFICULTIES ENCOUNTERED

37. DID CHUTE OPEN IMMEDIATELY? IF NO, GIVE REASON

☒ YES ☐ NO

38. ALTITUDE THAT CHUTE OPENED

Estimated 35 FEET

39. OPENING SHOCK WAS

UNKNOWN

☐ SLIGHT ☐ MODERATE ☐ SEVERE

40. BODY ATTITUDE AT OPENING

Horizontal

41. CONDITION OF CHUTE AFTER OPENING

Normal

42. CHUTE OSCILLATION PRESENT

☒ NONE ☐ SLIGHT ☐ MODERATE ☐ SEVERE

43. IF OSCILLATION WAS PRESENT, HOW WAS IT STOPPED?

44. WEATHER CONDITIONS DURING DESCENT (List in sequence)

Visual Flight Rules

45. TOPOGRAPHY OF LANDING SITE

Erosion ditches, rocky terrain, trees, brush

46. WAS BAILOUT OXYGEN CONNECTED?

☒ BEFORE EXIT ☐ AFTER EXIT ☐ NO ☐ N.A.

47. WAS BAILOUT OXYGEN USED? IF NOT, WHY?

☐ YES ☒ NO Pilot not wearing mask

48. WHEN WAS IT ACTIVATED?

☐ BEFORE EXIT ☐ AFTER EXIT

49. GIVE DIFFICULTIES ENCOUNTERED WITH BAILOUT OXYGEN AND THEIR CAUSE, IF ANY

50. WAS CHUTE HARNESS

☐ TIGHT ☒ SNUG ☐ LOOSE

51. WAS A SITTING POSITION IN SLING OBTAINED DURING DESCENT? IF NOT, WHY?

☐ NO ☐ YES ☐ NOT ATTEMPTED

52. SEAT CUSHION IF PROVIDED (Model/Type)

☐ NONE ☒ Seat Pan

53. WAS PARACHUTE LANYARD CONNECTED TO LIFE VEST & RINGS? IF NOT, WHY?

☐ NO ☐ YES

54. LIST TYPE OF PARACHUTE TRAINING COMPLETED BY THIS INDIVIDUAL

☐ NONE ☒ Ejection seat lecture, movie, and shot; Squadron lectures

55. IF ATTEMPT WAS MADE TO RELEASE PARACHUTE DURING DESCENT, WAS RELEASE ACTIVATED SUCCESSFULLY?

☐ YES ☐ NO

56. IF NO, GIVE REASON

57. IF G-SUIT, EXPOSURE SUIT, FULL OR PARTIAL PRESSURE SUIT WAS WORN, DID IT FIT PROPERLY? IF NOT, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR

☐ YES ☐ NO

58. WAS G-SUIT EQUIPPED WITH A SPRING-LOADED DISCONNECT ADAPTER? IF NO, GIVE REASON

☐ YES ☐ NO

59. LIST ALL ITEMS OF NON-STANDARD CLOTHING OR SURVIVAL EQUIPMENT UTILIZED

Air Force P-1A Hard Hat

60. WAS ANY ITEM OF EQUIPMENT LOST? IF YES STATE ITEM, WHEN LOST, AND REASON FOR LOSS.

☐ NO ☒ YES See attached sheet.

61. WAS ANY ITEM OF EQUIPMENT DISCARDED? IF YES, STATE ITEM, WHEN DISCARDED, AND REASON FOR DISCARD.

☐ NO ☐ YES

OTHER

G-60

CAPT (b) (6) Air Force hard hat (P-4A) was found approximately 15-20 feet away from him when the reporting Flight Surgeon reached him. CAPT (b) (6) elected to use the Air Force hard hat in preference to the standard Navy APH-5 by reason of not being able to achieve a proper fitting with the latter. It should be noted that said Air Force hard hat did not have a chin strap. The reporting Flight Surgeon feels that the lack of a chin strap and non-utilization of the Hardeman fittings were responsible for the loss of CAPT (b) (6) hard hat. It is probable that CAPT (b) (6) lost his hard hat on contact with the fence surrounding the reservation, immediately prior to contact with the ground.

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE (Continued)

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

SECKINGER, Neil Vincent

T2J-1

RESTRAINT HARNESS

19. INTEGRATED HARNESS SYSTEM MODEL/TYPE

MB-7 Par.Torso Harness

20. INTEGRATED?

☒ FULL ☐ PARTIAL

21. MODIFICATIONS, IF ANY STATE REASON

Rocket Jet Connector Reversed

22. DID INTEGRATED HARNESS FIT PROPERLY? IF NO, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR

☐ NO ☒ YES

23. INTEGRATED HARNESS FITTING WAS CONDUCTED BY

☐ WEARER ☐ FLIGHT SURGEON ☒ PARACHUTE RIGGER ☐ AVIATION EQUIPMENT OFFICER ☐ OTHER

24. IF SHOULDER HARNESS WAS USED, WAS IT

☐ LOCKED ☐ UNLOCKED ☐ TIGHT ☐ SLACK ☐ OTHER CONDITION **UNKNOWN**

HELMET

25. TYPE HELMET

AFH-5

26. LIST PRESCRIBED MODIFICATIONS

Chin and nape strap; Hardeman fittings

27. OTHER MODIFICATIONS AND REASON FOR THEM

None

28. DID HELMET FIT PROPERLY? IF NO, GIVE REASON

☒ YES ☐ NO

29. HELMET FITTING WAS CONDUCTED BY

☐ WEARER ☐ FLIGHT SURGEON ☒ PARACHUTE RIGGER ☐ AVIATION EQUIPMENT OFFICER ☐ OTHER

PARACHUTE

30. TYPE CHUTE

MB-7

31. LAST PACKING DATE

27 March 1961

32. MODEL/TYPE BAILOUT OXYGEN

F-151300-5

33. AUTOMATIC RIPCORDER, IF INSTALLED (Model and type)

☐ NONE **Master Specialty 1000-C**

34. DID AUTOMATIC RIPCORDER FAIL? IF YES, WHY?

☐ NO **See discussion of item H-6 for items G-34, 35, 36, 37, 38, 39, 40, & 41.**

35. WAS RIPCORDER ACTIVATION

☐ MANUAL ☐ AUTOMATIC

36. IF MANUALLY ACTIVATED STATE REASON AND ANY DIFFICULTIES ENCOUNTERED

37. DID CHUTE OPEN IMMEDIATELY? IF NO, GIVE REASON

☐ YES ☐ NO

38. ALTITUDE THAT CHUTE OPENED

FEET

39. OPENING SHOCK WAS

☐ SLIGHT ☐ MODERATE ☐ SEVERE

40. BODY ATTITUDE AT OPENING

41. CONDITION OF CHUTE AFTER OPENING

42. CHUTE OSCILLATION PRESENT

☐ NONE ☐ SLIGHT ☐ MODERATE ☐ SEVERE

43. IF OSCILLATION WAS PRESENT, HOW WAS IT STOPPED?

44. WEATHER CONDITIONS DURING DESCENT (List in sequence)

VFR

45. TOPOGRAPHY OF LANDING SITE

Ermon ditch, rocky terrain, trees, brush

46. WAS BAILOUT OXYGEN CONNECTED?

☒ BEFORE EXIT ☐ AFTER EXIT ☐ NO ☐ N.A.

47. WAS BAILOUT OXYGEN USED? IF NOT, WHY?

☐ YES ☒ NO **Pilot not wearing mask**

48. WHEN WAS IT ACTIVATED?

☒ BEFORE EXIT ☐ AFTER EXIT

49. GIVE DIFFICULTIES ENCOUNTERED WITH BAILOUT OXYGEN AND THEIR CAUSE, IF ANY

50. WAS CHUTE HARNESS

☐ TIGHT ☒ SNUG ☐ LOOSE

51. WAS A SITTING POSITION IN SLING OBTAINED DURING DESCENT? IF NOT, WHY?

☐ NO ☐ YES ☐ NOT ATTEMPTED

52. SEAT CUSHION IF PROVIDED (Model/Type)

☐ NONE **Seat Pan**

53. WAS PARASAIL LANTARD CONNECTED TO LIFE VEST OR RING? IF NOT, WHY?

☐ NO ☐ YES

54. LIST TYPE OF PARACHUTE TRAINING COMPLETED BY THIS INDIVIDUAL

☐ NONE **Ejection seat lecture, movie and photo Squadron lectures**

55. IF ATTEMPT WAS MADE TO RELEASE PARASAIL DURING DESCENT, WAS RELEASE ACTIVATED SUCCESSFULLY?

☐ YES ☐ NO

56. IF NO, GIVE REASON

57. IF G SUIT, EXPOSURE SUIT, FULL OR PARTIAL PRESSURE SUIT WAS WORN, DID IT FIT PROPERLY? IF NOT, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR

☐ YES ☐ NO

58. WAS G SUIT EQUIPPED WITH A SPRING-LOADED DISCONNECT ADAPTER? IF NO, GIVE REASON

☐ YES ☐ NO

59. LIST ALL ITEMS OF NON-STANDARD CLOTHING OR SURVIVAL EQUIPMENT UTILIZED

OTHER

60. WAS ANY ITEM OF EQUIPMENT LOST? IF YES STATE ITEM, WHEN LOST, AND REASON FOR LOSS.

☐ NO ☒ YES **See attached sheet**

61. WAS ANY ITEM OF EQUIPMENT DISCARDED? IF YES, STATE ITEM, WHEN DISCARDED, AND REASON FOR DISCARD.

☒ NO ☐ YES

SUPPLEMENT TO PAGE 4, SECTION G, VT-7 MOR 6-61 (SECKINGER, Neil Vincent)

G-60

LCDR SECKINGER's hard hat (APH-5) was lost, presumably, on his initial contact with the ground. Both chin strap and one Hardeman fitting were torn from the helmet (see enclosures 5-O and 5P). It is believed that non-utilization of the Hardeman suspension was responsible for the loss of LCDR SECKINGER's hard hat and, subsequently, for a portion of the severe and extensive cranio-cerebral trauma sustained on impact with the ground.

SECTION 4 - EMERGENCY EXIT FROM A/C AND SURVIVAL FA /RS

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

(b) (6)

T2J-1

5. E		E SUSPECTED, E-ESTABLISHED		REMARKS	
<input checked="" type="checkbox"/>	1.	EJECTION - Attempted			
<input checked="" type="checkbox"/>	2.	- Accomplished			
<input checked="" type="checkbox"/>	3.	- Through canopy			
YES	NO	EJECTION DIFFICULTIES ENCOUNTERED		IF YES, EXPLAIN DIFFICULTIES	
<input checked="" type="checkbox"/>	4.	- Prior to			
<input checked="" type="checkbox"/>	5.	- During			
<input checked="" type="checkbox"/>	6.	- Subsequent to			
<input checked="" type="checkbox"/>	7.	Give type and model of seat used		Seat Assembly, Pilot ejection 249-53009-61	
<input type="checkbox"/>	8.	BAIL OUT - Attempted			
<input type="checkbox"/>		- Accomplished			
9. ALTITUDE AT TIME OF EXIT (feet)		10. ATTITUDE OR MANEUVER OF A/C AT EXIT OR IMPACT		11. AIRSPEED	
ABOVE SEA LEVEL <u>52</u>		ABOVE TOPOGRAPHY <u>0</u>		Attempted aborted take off <u>110-115 kts</u>	
12. COLLISION OF A/C WITH		13. CONTROLLED?		14. POWER	
<input type="checkbox"/> GROUND	<input type="checkbox"/> WATER	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> UNKNOWN	<input type="checkbox"/> ON
15. WHEELS		16. FLAPS		17. CANOPY POSITION AT EXIT OR IMPACT	
<input type="checkbox"/> UP	<input type="checkbox"/> DOWN	<input type="checkbox"/> FULL	<input type="checkbox"/> UP	<input type="checkbox"/> PARTIAL	<input type="checkbox"/> OPEN
18. SEA STATE		19. AIR TEMP		20. WATER TEMP	
<u>84</u>		<u>84</u>		<u>84</u>	
21. A/C FLOATED		22. TIME IN WATER		23. TIME IN AIR	
<u>SEC</u>		<u>SEC</u>		<u>SEC</u>	
24. EXIT USED		25. IS THIS THE RECOMMENDED EXIT? IF NO STATE REASON FOR CHOICE		26. DIFFICULTIES WITH THIS EXIT WERE	
Ejection		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> IN REACHING	
27. STATE NATURE OF DIFFICULTY		<input type="checkbox"/> IN OPENING		<input type="checkbox"/> IN EXITING	
28. BODY POSITION DURING EXIT		29. LIST OTHER FACTORS NOT INDICATED ABOVE WHICH AFFECTED EXIT FROM A/C		Normal for ejection	

SURVIVAL FACTORS: Check factors below which are appropriate for this accident. Prepare a detailed narrative account of the factors checked below and attach to this form. Identify each item discussed by item number (e.g., H30, H31, etc.)

COMMUNICATIONS:		MAINTAINING BODY TEMPERATURE:	
<input type="checkbox"/> 30. Communicated position prior to mishap	<input type="checkbox"/> 50. Items used as shelter	<input type="checkbox"/> 51. Items used as clothing	<input type="checkbox"/> 52. Fire
<input type="checkbox"/> 31. Witnesses at scene	<input type="checkbox"/> 53. OTHER:	ENVIRONMENTAL HAZARDS:	
<input type="checkbox"/> 32. Electronic signal devices	<input type="checkbox"/> 54. Exposure to natural forces	<input type="checkbox"/> 55. Exposure to dangerous animals and plants	<input type="checkbox"/> 56. Unfriendly native population
<input type="checkbox"/> 33. Visual signal devices	<input type="checkbox"/> 57. OTHER:	TRAVEL:	
<input type="checkbox"/> 34. Auditory signal devices	<input type="checkbox"/> 58. Isolation	<input type="checkbox"/> 59. Psychological shock	<input type="checkbox"/> 60. Lack of motivation to survive
<input type="checkbox"/> 35. OTHER:	<input type="checkbox"/> 61. Boredom	<input type="checkbox"/> 62. Rationing, activities, and group coordination	<input type="checkbox"/> 63. OTHER:
SHELTER:		FOOD SOURCE:	
<input type="checkbox"/> 36. Life raft	<input type="checkbox"/> 64. Prepared survival rations	<input type="checkbox"/> 65. Animals/plants	<input type="checkbox"/> 66. OTHER:
<input type="checkbox"/> 37. Parachute	SURVIVAL TRAINING RECEIVED PRIOR TO MISHAP:		
<input type="checkbox"/> 38. A/C structure	<input type="checkbox"/> 67. Survival course in basic - effective		
<input type="checkbox"/> 39. Natural shelter	<input type="checkbox"/> 68. Survival course in this instance.		
<input type="checkbox"/> 40. Man-made shelter			
<input type="checkbox"/> 41. OTHER:			
WATER SOURCE:			
<input type="checkbox"/> 42. Desalter kit, seawater or solar still			
<input type="checkbox"/> 43. Rain, dew, snow, ice, etc.			
<input type="checkbox"/> 44. Processed beverages			
<input type="checkbox"/> 45. Canteen, thermos, water breaker, etc.			
<input type="checkbox"/> 46. Streams, ponds, wells, etc.			
<input type="checkbox"/> 47. OTHER:			

MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT - PAGE 5
OPNAV FORM 3750-8D (REV. 5-58)

OPNAV REPORT 5750-7

SECTION 4 - EMERGENCY EXIT FROM A/C AND SURVIVAL FACTORS

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

SECKINGER, Neil Vincent

T2J-1

5	E	5-SUSPECTED, E-ESTABLISHED	REMARKS
<input checked="" type="checkbox"/>		1. EJECTION - Attempted	
<input checked="" type="checkbox"/>		2 - Accomplished	
<input checked="" type="checkbox"/>		3 - Through canopy	
YES	NO	EJECTION DIFFICULTIES ENCOUNTERED	IF YES, EXPLAIN DIFFICULTIES
<input checked="" type="checkbox"/>		4 - Prior to	
<input checked="" type="checkbox"/>		5 - During	
<input checked="" type="checkbox"/>		6 - Subsequent to	
<input checked="" type="checkbox"/>		7 Give type and model of seat used	See attached sheet
<input checked="" type="checkbox"/>		8 BAIL OUT - Attempted	Seat Assembly, pilot ejection 249-53009-61
		- Accomplished	

9 ALTITUDE AT TIME OF EXIT (feet)		10 ATTITUDE OR MANEUVER OF A/C AT EXIT OR IMPACT		11 AIRSPEED	
ABOVE SEA LEVEL 50 ABOVE TOPOGRAPHY 0		Attempted Aborted Take-off		110-115 kts	
12 COLLISION OF A/C WITH		13 CONTROLLED?		14 POWER	
<input type="checkbox"/> GROUND <input type="checkbox"/> WATER		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> UNKNOWN		<input type="checkbox"/> ON <input type="checkbox"/> OFF	
15 WHEELS		16 FLAPS		17 CANOPY POSITION AT EXIT OR IMPACT	
<input type="checkbox"/> UP <input type="checkbox"/> DOWN		<input type="checkbox"/> FULL <input type="checkbox"/> UP <input type="checkbox"/> PARTIAL		<input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED <input checked="" type="checkbox"/> JETTISONED	
18 SEA STATE		19 AIR TEMP		20 WATER TEMP	
		84 °F		84 °F	
21 A/C FLOATED		22 TIME IN WATER		23 TIME IN RAFT	
		SEC			
24 EXIT USED		25 IS THIS THE RECOMMENDED EXIT? IF NO STATE REASON FOR CHOICE.			
Ejection		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
26 DIFFICULTIES WITH THIS EXIT WERE		27 STATE NATURE OF DIFFICULTY			
<input type="checkbox"/> IN REACHING <input type="checkbox"/> IN OPENING <input type="checkbox"/> IN EXITING					
28 BODY POSITION DURING EXIT					
Normal for ejection					

29. LIST OTHER FACTORS NOT INDICATED ABOVE WHICH AFFECTED EXIT FROM A/C

SURVIVAL FACTORS: Check factors below which are appropriate for this accident. Prepare a detailed narrative account of the factors checked below and attach to this form. Identify each item discussed by item number (e.g., H30, H31, etc.).

COMMUNICATIONS:		MAINTAINING BODY TEMPERATURE:	
30. Communicated position prior to mishap		50. Items used as shelter	
31. Witnesses at scene		51. Items used as clothing	
32. Electronic signal devices		52. Fire	
33. Visual signal devices		53. OTHER:	
34. Auditory signal devices		ENVIRONMENTAL HAZARDS:	
35. OTHER:		54. Exposure to natural forces	
TRAVEL:		55. Exposure to dangerous animals and plants	
36. LAND		56. Unfriendly native population	
37. WATER		57. OTHER:	
SHELTER:		NORAL:	
38. Life raft		58. Isolation	
39. Parachute		59. Psychological shock	
40. A/C structure		60. Lack of motivation to survive	
41. Natural shelter		61. Boredom	
42. Man-made shelter		62. Rationing, activities, and group coordination	
43. OTHER:		63. OTHER:	
WATER SOURCE:		FOOD SOURCE:	
44. Desalter kit, seawater or solar still		64. Prepared survival rations	
45. Rain, dew, snow, ice, etc.		65. Animals/plants	
46. Processed beverages		66. OTHER:	
47. Canteen, thermos, water breaker, etc.		SURVIVAL TRAINING RECEIVED PRIOR TO MISHAP:	
48. Streams, ponds, wells, etc.		67.	
49. OTHER:		Survival course in basic; effective use shown in this instance.	

H-6

LCDR SECKINGER did not separate from his seat, and he came to rest, in the seat, 599 feet from the end of the runway. CAPT (b) (6) realized that there was no runway overrun and initiated ejection at the end of the runway. Ejection control was in the front cockpit and, therefore, CAPT (b) (6) had ejection control for both pilots.

Ejection system.

a. Rear seat S/NH-407

- (1) Neither face curtain initiator (T-30E1) fired.
- (2) Neither face curtain cable cutter fired.
- (3) Harness release gun was not fired.
- (4) Neither the seat bottom bladder nor its initiator (T31E1) inflated or fired.
- (5) Neither back bladder nor its initiator (T-31E1) inflated or fired.
- (6) The "D" ring handle was pulled and the 2 (T-30E1) initiators were fired.
- (7) The seat drogue gun was fired.
- (8) The aneroid unit - Arming pin was not pulled.
- (9) Evidence strongly supports the fact that no pivot pin was in the striker bellcrank at the time of ejection. (See encl. 5N and 5W) Striker bellcrank engagement with the striker pin on the seat bulkhead produced sufficient rotation to pull firing pin from drogue gun, but the stroke was not sufficient to pull the aneroid aiming pin.

See Section I of this report.

MEDICAL OFFICER'S REPORT OF A / ACCIDENT. INCIDENT. OR GROUND ACCIDENT - PAGE 6
OPNAV FORM 3750-8E (REV. 5-58)

OPNAV REPORT 3750-7

SECTION 1 - PATHOLOGICAL FACTORS (Use A to denote ANTE MORTEM; P for POST MORTEM, when known and applicable.)

1. NAME OF INDIVIDUAL (Last, first, middle) **(b) (6)** MODEL A/E **72J-1**

2. AGE **31** 3. HEIGHT **72** INCHES 4. WEIGHT **175** 5. LOCATION AND DIRECTION FACING AT TIME OF ACCIDENT **Pilot - forward cockpit; facing forward** INJURY CODE **C**

7. UNCONSCIOUSNESS ☒ SHORT DURATION LITTLE SIGNIFICANCE ☐ OTHER (give time) **None** 8. INTERNAL INJURIES (Non-fatal cases) **None**

9. CEREBRAL CONCUSSION ☐ MILD ☐ SERIOUS ☐ CRITICAL ☐ FATAL **None** 10. FACIAL INJURIES (N. F. C.) **None** 11. INTRA-ORAL INJURIES **None**

12. MINDS EYE INJURIES ☐ RIGHT ☐ LEFT 13. MAJOR EYE INJURIES ☐ RIGHT ☐ LEFT

14. TYPE OF FRACTURE **(b) (6)**
SIMPLE
COMPOUND
COMMINATED
DIS- LOCATION
15. AMPUTATIONS/AVULSIONS (State Parts)
16. LIST PRE-EXISTING PHYSICAL DEFECTS PRESENT AT TIME OF POST CRASH EXAMINATION **None**

17. SOFT TISSUE INJURIES
HEAD (N. F. C.)
NECK
THORAX
ABDOMEN
EXTREMITIES
LACERATIONS
MILD MODERATE SEVERE
CONTUSION/SPRAIN/STRAIN
MILD MODERATE SEVERE
ABRASIONS
MILD MODERATE SEVERE
18. ☐ DROWNED
19. ☐ ASPHYXIATED
20. SHOCK
MILD MODERATE SEVERE
21. EXPOSURE
MILD MODERATE SEVERE

22. BURNS
DEGREE 1ST 2ND 3RD
AREA
23. EXTENT OF CARBONIZATION
NONE COMPLETE
ARE TISSUE SPECIMENS OBTAINABLE? YES NO

NOTE: Attach a detailed narrative account of injuries, cause, structures causing injury, magnitudes of force, and include whether ANTE- OR POST-MORTEM if determined. It is necessary to give as clear a picture of injury cause and sequence as possible.

24. ADMITTED TO SICK LIST? IF YES, GIVE DIAGNOSIS **(b) (6)** 25. DIAGNOSIS NO. (AFMOP-P-100) **8360** 26. ESTIMATED STAY ON SICK LIST **See attached sheet**

27. GROUNDWATER? IF YES GIVE REASON ☐ YES ☐ NO 28. ESTIMATED DURATION **DAYS**

29. PRIMARY CAUSE OF DEATH (Use Basic Diagnostic Nomenclature, AFMOP-P-100) 30. SECONDARY CAUSE OF DEATH

31. AUTOPSY PERFORMED? ☐ YES ☐ NO 32. PROTOCOL ☐ ATTACHED ☐ WILL BE FORWARDED 33. AUTOPSY CONDUCTED BY ☐ PATHOLOGIST ☐ FLIGHT SURGEON 34. IF FLIGHT SURGEON DOES AUTOPSY USE "AUTOPSY GUIDE FOR A/C ACCIDENT FATALITIES", AFMOP-P-100.

24. SPECIMEN	TEST PERFORMED	RESULTS	25. SPECIMEN	TEST PERFORMED	RESULTS
BLOOD	1	See attached sheet	TISSUE (CNS)		
	2		MUSCLE		
	3		VISCERA		
URINE			OTHER		
24. CONTENTS					

25. IF ULTRAVIOLET LIGHT OR OTHER SPECIALIZED INVESTIGATIVE PROCEDURES WERE USED AT THE CRASH SITE OR AUTOPSY, LIST THEM IN THIS SPACE, FOR EACH ENTRY IN THIS SPACE A NARRATIVE ACCOUNT OF THEIR RESULTS AND INTERPRETATION WILL BE ATTACHED.

SUPPLEMENT TO PAGE 6, SECTION I, VT-7 MCR 6-61 (b) (6)

I-26

(b) (6)



I-34

(b) (6)



MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT - PAGE 6
OPNAV FORM 3750-8E (REV. 5-58)

SPRINT REPORT 1750-2

SECTION 1 - PATHOLOGICAL FACTS (Use A to denote ANTE-MORTEM; P for POST-MORTEM, when known and applicable.)

1. NAME OF INDIVIDUAL (Last, first, middle) **BECKINGER, Neil Vincent** MODEL A/C **T2J-1**

2. AGE **38** 3. HEIGHT **66 1/2** INCHES 4. WEIGHT **213** 5. LOCATION AND DIRECTION FACING AT TIME OF ACCIDENT **Aft cockpit - facing forward** 6. INJURY CODE **A**

7. UNCONSCIOUSNESS ☐ SHORT DURATION LITTLE SIGNIFICANCE ☐ OTHER (give time) 8. INTERNAL INJURIES (Non-fatal cases)

9. CEREBRAL CONCUSSION ☐ MINOR ☐ SERIOUS ☐ CRITICAL ☒ FATAL 10. FACIAL INJURIES (R. F. F.) 11. INTER-ORAL INJURIES **None**

12. MINOR EYE INJURIES ☐ RIGHT ☐ LEFT 13. MAJOR EYE INJURIES ☐ RIGHT ☒ LEFT

14. TYPE OF FRACTURE **SKULL** **VERTEBRAE (Specify No.)** **SHOULDER GIRDLE** **RIBS** **PELVIS** **UPPER ARM** **LOWER ARM** **HAND** **UPPER LEG** **LOWER LEG** **FOOT**

CRAN **FACIAL** **CERV.** **HOR.** **LUMBAR** **SACRAL** **COCYX** **R** **L** **R** **L** **R** **L** **R** **L** **R** **L** **R** **L**

COMPOUND **COMMINUTED** **DISLOCATION**

SHOULDER **ELBOW** **WRIST** **HIP** **KNEE** **ANKLE**

HAND **FOOT**

15. AMPUTATIONS/AVULSIONS (State Parts) 16. LIST PRE-EXISTING PHYSICAL DEFECTS PRESENT AT TIME OF POST CRASH EXAMINATION

None

17. SOFT TISSUE INJURIES **LACERATIONS** **CONTUSION/SPRAIN/STRAIN** **ABRASIONS**

WILD **MODERATE** **SEVERE** **WILD** **MODERATE** **SEVERE** **WILD** **MODERATE** **SEVERE** 18. ☐ BURNED

19. ☐ ASPHYXIATED

20. ☐ MILD ☐ MODERATE ☐ SEVERE

21. ☐ MILD ☐ MODERATE ☐ SEVERE

22. ☐ BURNS ☐ FROST BITE

23. EXTENT OF CARBONIZATION: ☐ NONE ☐ COMPLETE

NOTE: Attach a detailed narrative account of injuries, cause, structures causing injury, magnitudes of force, and include whether ANTE- OR POST-MORTEM if determined. It is necessary to give as clear a picture of injury cause and sequence as possible.

24. ADMITTED TO SICK LIST? IF YES, GIVE DIAGNOSIS 25. DIAGNOSIS NO. (INFORMED PAIN)

26. ESTIMATED STAY ON SICK LIST **DAYS**

27. GROUNDWATER? IF YES GIVE REASON 28. ESTIMATED DURATION **DAYS**

29. PRIMARY CAUSE OF DEATH (Use Basic Diagnostic Nomenclature, NAMED PAIN) 30. SECONDARY CAUSE OF DEATH

31. AUTOPSY PERFORMED? ☐ YES ☐ NO 32. AUTOPSY CONDUCTED BY ☐ PATHOLOGIST ☐ FLIGHT SURGEON

33. SPECIMEN **TEST PERFORMED** **RESULTS** **SPECIMEN** **TEST PERFORMED** **RESULTS**

BLOOD **1** **CO** **less than 10%** **TISSUE (LCS)** **Lactic Acid** **175 mg**

2 **Alcohol** **none found** **MUSCLE** **OTHER:**

34. IF ULTRAVIOLET LIGHT/OTHER SPECIALIZED INVESTIGATIVE PROCEDURES WERE USED AT THE CRASH SITE OR AUTOPSY, LIST THEM IN THIS SPACE. FOR EACH ENTRY IN THIS SPACE A NARRATIVE ACCOUNT OF THEIR RESULTS AND INTERPRETATION WILL BE ATTACHED.

SUPPLEMENT TO PAGE 6, SECTION I, VT-7 MOR 6-61 (SECKINDER)

(b) (6)



C O P Y

CLINICAL RECORD

AUTOPSY PROTOCOL

DATE AND HOUR DIED 5-25-61 0900	A. M. P. M.	DATE AND HOUR AUTOPSY PERFORMED 5-26-61 0830-1005	A. M. P. M.	CHECK ONE		
PROSECTOR (b) (6) LT MC USNR		ASSISTANT M. E. ROHNS, LT MC USNR		FULL AUTOPSY	HEAD ONLY	TRUNK ONLY
CLINICAL DIAGNOSES (Including operations)				I		

Aircraft accident. This LCDR was taking off from South Field, NAS, Kingsville, Tex. in a T2J-1, BUONO 118222 when trouble developed and the aircraft crashed, with the pilot sustaining fatal injuries. Time of crash was 0900 on 25 May 1961.

CORONER'S CASE: R. J. Sims, County Coroner
Kleberg County
1217 West Richard
Kingsville, Texas

PATHOLOGICAL DIAGNOSES (PRELIMINARY)

(b) (6)

APPROVED-SIGNATURE (b) (6) LT MC USNR		MILITARY ORGANIZATION (USN/USMC) LTMC/USN		AGE 38	SEX Male	RACE Cauc.	REGISTER NO. 101091-30	AUTOPSY NO. 161-65
PATIENT'S LAST NAME-FIRST NAME-MIDDLE NAME SECKINGER, M-11 V.						WARD NO. DOA-Morgue		

(NAME OF HOSPITAL OR OTHER MEDICAL FACILITY AND LOCATION)

U. S. GOVERNMENT PRINTING OFFICE 16-58218-5

AUTOPSY PROTOCOL
Standard Form 508

ENCL. (1)

U. S. NAVAL HOSPITAL
CORPUS CHRISTI, TEXAS

NH32-25-jej
6120/1
A61-25
26 May 1961

SECKINGER, Neil V., LCDR/USN, (b) (6) J-101091-DD

GROSS DESCRIPTION

EXTERNAL EXAMINATION: (b) (6)



SECKINGER, Neil V., LCDR/USN,

(b) (6)

J-101094-DD

MH32-25-jej

6120/1

Δ61-25

26 May 1961

-2-

INTERNAL EXAMINATION: (b) (6)

THORACIC CAVITY: (b) (6)

ABDOMINAL CAVITY: (b) (6)

CRANIAL CAVITY: (b) (6)

HEART: (b) (6)

AORTA: (b) (6)

LUNGS: (b) (6)

OFFICE OF THE
JUDGE ADVOCATE GENERAL
U.S. AIR FORCE
WASHINGTON, D.C.

SECKINGER, Neil V., LCDR, USN, (b) (6) J-101094-DD

NH32-25-JeJ
6120/1
A61-25
26 May 1961

-3-

(b) (6)

GASTROINTESTINAL TRACT:

ESOPHAGUS: (b) (6)

STOMACH: (b) (6)

DUODENUM AND SMALL INTESTINE: (b) (6)

APPENDIX: (b) (6)

COLON: (b) (6)

LIVER: (b) (6)

GALLBLADDER AND BILIARY TRACT: (b) (6)

PANCREAS: (b) (6)

SPLEEN: (b) (6)

ADRENALS: (b) (6)

KIDNEYS: (b) (6)

URETERS: (b) (6)

URINARY BLADDER: (b) (6)

PROSTATE: (b) (6)

SECKINGER, Neil V., LCDR, USN,

(b) (6)

J-101094-DD

NH32-25-jcj

6120/1

..61-25

26 May 1961

-4-

TESTES:

(b) (6)

THYROID:

(b) (6)

LYMPH NODES:

(b) (6)

MUSCULOSKELETAL SYSTEM:

(b) (5)


SPIN:

(b) (6)

RADIOGRAPHIC REPORT: SECKINGER, NEIL VINCENT, LCDR USN, (b) (6)
AGE 38; SEX MALE; BODY SERIES REQUESTED BY (b) (6) 5-25-61; FATALITY
FOLLOWING T2J-1 CRASH (VT-7 NAAS KINGSVILLE, TEXAS)

KINGSVILLE FILMS

BODY SERIES: (b) (6)



USNH CC TEX

/s/ RCO

(b) (6)

LT MC USN

RADIOGRAPHIC REPORT: (b) (6) CAPT USMC; HT. (b) (6)
AGE 31; SEX MALE; FOLLOWING T2J-1 CRASH (VT-7 NAAS KINGSVILLE, TEXAS)

#2266-61

C-SPINE 5/25/61:

(b) (6)

USNH CC TEX

(b) (6)

LT MC USN

ENCLOSURE (h), VT-7 MOR 6-61

Health and Sick Call Records are not considered pertinent to this accident.

Recommendations for Corrective Action

1. It is recommended that closer attention by supervisory authority be exercised both in adherence to Standard Operating procedures and in review of maintenance procedures. A continuous review of procedures by all personnel, flight and maintenance, must be examined periodically in an effort to remain cognizant of changes required or occurrences of non-compliance with standard operating procedures and/or check sheets.

2. It is recommended that both the intermediate and major check sheets on the maintenance of the ejection seats be revised so that the check sheet shows each item to be checked, especially the striker arm pivot pin, which is not listed on the check sheet. It is further recommended that no work be accomplished on the ejection system without a work order being issued.

3. It is recommended that only qualified personnel be permitted to sign off gripes on/or inspection of the ejection seat system. If the number of qualified personnel assigned do not meet the requirements of the command, then a strenuous, conscientious effort must be exerted to train enough other personnel to meet the needs. Special attention must be given to selecting only the most highly qualified personnel to be used as instructors.

4. It is believed that if CAPT (b)(6) had been wearing his oxygen mask at the time of his low level ejection, he would have died from suffocation. This belief is based on the figures of usable time/quantity of the bailout bottle, which is activated at ejection. The emergency oxygen supply is capable of providing approximately 2 to 3 minutes of normal breathing at sea level. From the time of initiation of ejection until help arrived for CAPT (b)(6) 5 to 6 minutes had elapsed and CAPT (b)(6) was unconscious from the time he contacted the ground.

In view of the above it is recommended that the Bureau of Weapons immediately initiate a study of the problem, which is to insure that outside air be made available to the pilot as soon as the emergency oxygen supply has been depleted.

Summary and Conclusions

No sociological, psychological, physiological, or pathological factors are judged to be operative in the genesis of this accident.

The primary contributing cause factor in this accident is the fact that the aircraft did not become airborne due to a suspected failure or malfunction of the elevator control system.

The contributing pilot cause factor in this accident is that a flaps up take-off was attempted, which required almost the full length of the runway for take-off roll and abort stopping distance. This same take-off attempt with flaps down left 1500 feet of runway remaining after take-off roll and abort stopping distance.

This take-off should never have been attempted for the following reasons:

1. Both pilots were Assistant Maintenance Officers and should have realized the significance of taking an aircraft that had discrepancies.
2. The low oil pressure would have been noted prior to commencing take-off roll had the correct procedure of checking engine instruments been used.
3. The speed brakes not extended.

The procedure of going over check-off lists while taxiing on any type of flight is in violation of standard operating procedures of this squadron.



FOR 6-61 TRA 17 SAAS KINGSTILLE, TEXAS T2J-1 BU NO 148222. IMPACT DATA TO
SAFETY AND SURVIVAL EQUIPMENT UNIT: (b) (6)




MOR 6-61 TO 17 1115 FIVE, TEXAS T2J-1 WIND 148222. 1 PAGE PA 1 1 1
OFF T2J-1 WIND 148222. 1 PAGE PA 1 1 1
(b) (6)



MOR 6-61 TRACON 7 ELLS KINGSVILLE, TEXAS. T2J-1 WNO 118222. IMPACT DATA E
TO SAFETY AND SURVIVAL EQUIPMENT. CO-PILOT: SECKINGER, J.V.




MOR 6-61 TRACON 7 NAS KINGSVILLE, TEXAS. T2J-1 HUNO 148222. IMPACT DAMAGE
TO SAFETY AND SURVIVAL EQUIPMENT. CO-PILOT: SECKINGER, W.V.



CONTINUING SA TRACON 7 RAR 6-61 T2J-1 BUWO 140222 P1147 (b) AIRCRAFT PATH: LAIRMAN
 FROM TAKE OFF SPOT TO PLACE WHERE WRECKAGE CAME TO A STOP. DRAWING IS TO SCALE. SPECIAL
 HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 70 OPNAVINST 3750.6D.

(5)
 TENC

NOTE
ALL DISTANCES
MEASURED FROM
END OF RUNWAY
DRAWN TO SCALE






ENCLOSURE 6B TIRANOV 7 AAR 6-61 020-1 BUNO 118222. PILOT: (b)(6) VIEW OF
WRECKAGE WHILE STANDING IN BOTTOM OF STREAM LOOKING TOWARD THE RUNWAY. IT
IS ESTIMATED THAT THE STREAM BED IS ABOUT 35 FEET BELOW RUNWAY LEVEL. SPE-
CIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 70 OPNAVINST 3750.6D.



ENCLOSURE 62 TRANON 7 AAR 6-61 T2J-1 BUN 145222. PILOT: (b) (6) CLOSE-UP
VIEW OF MAIN WRECKAGE SHOWING EXTENT OF BURN DAMAGE. THE RIGHT WING, COCKPIT
AREA AND TOP OF FUSELAGE WERE COMPLETELY CONSUMED BY THE ENSUING FIRE. SPEC-
IAL HANDLING REQUIRED IN ACCORDANCE WITH TCM 24PH 70 OCTAVIST 3750.60.



ENCLOSURE 6J TRARON 7 AAR 6-61 T2J-1 BUNO 118222 PILOT: (b)(6) VIEW OF
BOTTOM OF CANOPY ACTUATOR SHOWING THE THREADS OF GAS TUBE FITTING ON ACTU-
ATOR IN GOOD CONDITION. THIS INDICATES GAS TUBE WAS NOT CONNECTED TO THE
FITTING WHEN ACCIDENT OCCURRED. SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70 OPNAVINST 3750.6D.




ENCLOSURE 6: T-1 ON 7 APR 66 6-61 T2J-1 CNO 11,8222. PILOT: (b) (6) VICTIM OF
CRASH AT UP WIND END OF HIGHWAY 17. (A) BURNED SPOT. (B) MAIN WRECKAGE. (C)
CAPT. SMITH'S SEAT. (D) CAPT (b) (6) POSITION. PART OF PARACHUTE VISIBLE
THROUGH THE TREES. (E) LCDR. SECKINGER AND SEAT. SPECIAL HANDLING REQUIRED
IN ACCORDANCE WITH PARAGRAPH 70, OPNAVINST 3750.6D .



ENCLOSURE 6D TERROR 7 AAR 6-61 T2J-1 BUINO 1148222 PILOT: (b) (6) WHERE
CAPT. (b) (6) SEAT CAME TO REST. SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70 OF NAVINST 3750.6D.




ENCLOSURE 6E TRARON 7 AAR 6-61 T2J-1 HUNG 148222. PILOT: (b) (6). WHERE CAPT. (b) (6) PARACHUTE CANOPY LANDED. CAPT. (b) (6) WAS ON OTHER SIDE OF FENCE HAVING GONE THROUGH THE AREA INDICATED BY THE CIRCLE. CAPT. (b) (6) HIT THE TOP OF THE FENCE IN LOWER PART OF THE CIRCLE. SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 70, OPNAVINST 3750.6D.



ENCLOSURE 6F TRARON 7 AAR 6-61 T2J-1 BUNO 148222. PILOT: (b)(6). ARROW
POINTS TO AREA WHERE LCDR. SECKINGER AND HIS SEAT CONTACTED THE GROUND. SPE-
CIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 70 OPNAVINST 3750,6D.



ENCLOSURE 6G TRARON 7 AAR 6-61 T2J-1 HUNG 118222. PILOT: (b) (6). WHERE
LCDR. SECKINGER AND SEAT CAME TO REST. THIS WAS 25 FEET FROM WHERE CONTACT
WITH THE GROUND WAS MADE. SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PAR-
AGRAPH 70 OPNAVINST 3750.6D.



ENCLOSURE 61 THARON 7 AAR 6-61 T23-1 BMT 145222 PILOT: (b) (6) WHEN
 SHOWING THAT THE ARM PIVOT CLEVIS IS IN THE CORRECT POSITION. THE CLEVIS
 TO BE IN THE POSITION AS INDICATED BY ENCLOSURE 61. (A) BELIEVE AIR (B)
 WHERE PIN SHOULD BE. SPECIAL HANDLING REQ IRE. IN ACCORDANCE WITH NA A-
 00001 70 OPNAVINST.3750.6D.



ENCLOSURE 6H TRARON 7 AAR 6-61 T2J-1 BUNO 148222 PILOT: (b) (6) VIEW
OF LEFT SIDE OF LCDR. SECKINGER'S SEAT. THIS PHOTOGRAPH WAS TAKEN AT
THE SCENE BEFORE PILOT OR SEAT WERE MOVED. ARROW INDICATES POSITION OF
EJECTION SEAT STRIKER MECHANISM BELLCRANK. FOLLOWING PHOTOGRAPH (ENC. 6I)
SHOWS COMPLETE BELLCRANK. SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH
PARAGRAPH 70 OPNAVINST 3750.6D.